

SURVEY & REMONUMENTATION

1999 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAR 23 2000

For corners in

SECTION
Genesee County Located In: Davison Corner Code # E-5
5

1. Public Land Survey	T	7N	R	8E	E-5
	T		R		
	T		R		
	T		R		
2. Property Controlling	S	T	R		
in Section	S	T	R		
3. Miscellaneous	S	T	R		
Property in Section	S	T	R		

4. Lot No. Recorded Plat
5. Private Claim

I, David J. Kenney, in a field survey on November, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

1822 G.L.O. Joseph Wampler D.S.
1973 L.C.R.C. L 1863, P. 102 by Karal R. Piotrowski, R.L.S. #9685
Found pipe, 3 accessories
1974 Rowe Engineering, Section Corner Card, Found 3/4" pipe, 4 accessories
1975 L.C.R.C. L 1906, P. 400 by Ronald W. Keller, R.L.S. 20707
Found 1/2" pipe, 3 accessories
1978 G.C.R.C. Court Street plans, Found 1" pipe set monument box; 4 accessories
1978 G.C.R.C. Gale Road plans, Found 1" pipe, 3 accessories
1985 Survey L2330, P. 85 by Joseph A. Wizynajtyts, Found 3/4" bar, 3 accessories
1988 Unrecorded survey by Carl H. Carlson, R.L.S. #9189, Found 1/2" pipe, 3 accessories
1993 Survey L 3410, P. 635 by James E. Kovas, R.L.S. #33138, Found monument, no accessories

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-5 Section Corner, Section 8,9,16,17, T7N-R8E, Davison Township

Found monument box only, nothing inside. 1 accessory from L.C.R.C. 1973 (S36°W, 69.82' power pole), 1978 G.C.R.C. Court Street plans 1 accessory (S35°W, 70.20' nail and tag in power pole), 1978 G.C.R.C. Gale Road plans, 2 accessories (S35°W, 70.20' nail and tag in power pole and East 33.98' centerline of Bell Telephone box), 1988 unrecorded survey 1 accessory (S50°W, 69.8' telephone pole).

In the field I crossed in the two accessories from G.C.R.C. Gale Road plans to establish E-5. Using this point E-5 to D-5 measures 2484.74' which agrees with the 1993 survey by Wade-Trim. The distance from E-5 to E-4 measures 2640.65' which also agrees. The angle from West-North measures 89°41'11" and Wade-Trim had 89°42'51". Also verified said point with the plat of "Glenwood Estates" monumentation as recorded in L. 64, P. 3 & 4, in the NE 1/4 of Section 17. Found monumentation on the East side of Gale Road set by Carl H. Carlson, R.L.S. #9189, verified alignment and offsets from E-5 as re-established.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-5 Section Corner, Section 8,9,16,17, T7N-R8E, Davison Township

Set 1/2" iron with Kraft cap in monument box
S45°E 59.34 Set nail and GCRC tag S. face 7" Pine
East 56.71 Set nail and GCRC tag S. face 8" Maple
East 33.8 W. face General Telephone Cable box
S35°W 70.00 Found nail and Dega tag in power pole
S80°W 95.08 Found nail N. face 18" Hickory

Ratified by Genesee County Peer Group November 17, 1999. I the standard Bernstein monument (3 1/4" d. brass cap stamp "Genesee County Remonumentation Corner, 1999" with 30" 3/8" O.D. stainless steel tube over monument box.

Signed by

Date December 27, 1999

Surveyor's Michigan License No. 39088