

SURVEY &
REMONUMENTATION
APR 07 1995
COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

REMONUMENTATION CORNER UNDER P.A. 345, MICHIGAN

For corners in

GENESEE

(County)

Located In:

Corner Code: H

1. Public Land Survey T 9N R 7E K-3
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

RECORDED

REC

APR 14 2 47 PM '94

GENESEE COUNTY

DEED LIBER 2528 PAGE 810

14750

9.00 Filed & Recd

Register of Deeds Stamp & File Number

I, RICHARD H. KRAFT, in a field survey on NOVEMBER 18, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1822 - GLO HORATIO BALL, SET POST

1878 - S.N. BEDIN, FOUND STONE & WHITE CROCK
SET POST & STONE, LIST 1 ACCESSORY

1880 - M.B. STAGE, SET STAKE
LIST 2 ACCESSORIES

1930 - G.C.R.C., FOUND STONE
LIST 5 ACCESSORIES

1972 - H. DORCEY, FOUND 1/2" RE-ROD IN
MONUMENT BOX
LIST 2 ACCESSORIES

1973 - LCRC, FOUND MONUMENT BOX
LIST 4 ACCESSORIES

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 GENESEE COUNTY REMONUMENTATION PROGRAM
RECOVERED RE-ROD IN MONUMENT BOX &
2 ACCESSORIES FROM 1972

I CONCLUDE THAT THE CORNER HAS LONG BEEN
PERPETUATED & DOESN'T SEEM TO HAVE CHANGED
SINCE 1972. THE RECOVERED ACCESSORIES SHOW
IT IS IN THE SAME POSITION. I ACCEPT IT AS A
FAITHFUL AND CAREFUL RESTORATION OF THE
POSITION OF THE ORIGINAL CORNER.

APPROVED BY GENESEE COUNTY PEER REVIEW GROUP,
DECEMBER 1, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

ACCESSORIES:

N 45°E 33.25' SET NAIL/G/C/ REMON TAG IN PAVEMENT
S 70°E 58.80' CONCRETE R/W MARKER
S 60°E 86.05' SET NAIL/G/C. REMON TAG IN 4" OAK
WEST 48.83' SET NAIL/G.C. REMON TAG IN 8" OAK
N 45°W 42.23' FOUND NAIL & TAG IN POWER POLE

I SET THE STANDARD BERNSTEN MONUMENT
(3 1/4" D. BRASS CAP STAMPED "GENESEE
COUNTY REMONUMENTATION CORNER, 1993"
WITH 2 3/8" O.D. STAINLESS STEEL TUBE
OVER RE-ROD IN MONUMENT BOX

Signed by

Richard H. Kraft

Date

Nov. 19, 1993

Surveyor's Michigan License No. *10064*

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

E