

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Gladwin  
(County)

Located In

Corner Code #

1. Public Land Survey T R  
T R  
2. Property Controlling in Section S 11 T 18N R 1E 3  
S 11 T 18N R 1E 4  
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on March 26, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

3 - None

4 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

3 - N 1/16 Corner common to Section 10 & 11, T18N, R1E - Set 2" Alum. Cap on 5/8" x 34" rebar per Standard BLM procedure. Falls on W'ly edge of old N-S 2-track Rd. Bed. Also found a 1/2" rebar is S31°55'W 8.86' from this set 2" Alum. Cap. Origin or purpose of 1/2" rebar is unknown.

4 - NW 1/16 Corner Section 11, T18N, R1E - Set 2" Alum. Cap on 5/8" x 34" rebar per Standard BLM procedure. A 1/2" x 1/2" angle iron of unknown origin was found N41°51'E 13.60' of 4'. N-S Cable in trees is 11'± E. E-W Cable in trees is 10'± N. S45°W 42' to centerline of 2-track.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar. East 33.00' to set 2" Alum. Cap on 5/8" x 34" rebar on line with Cedar post with loc. tag. N58°E 77.26' to set N & T in NW side 6" Oak S49°E 50.52' to set N & T in SW side 6" Oak S50°W 22.59' to set N & T in SE side 8" Oak S31°55'W 8.86' to Fd. 1/2" rebar

4 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar Set Blue Carsonite Post with Loc. Tag 1' NE. N53°E 23.82' to set N & T in NW side 9" Oak S18°E 32.33' to set N & T in E. side 8" R. Pine S31°W 20.02' to set N & T in E. side 7" Oak N43°W 15.10' to set N & T in SW. side 7" R. Pine N41°51'E 13.60' to Fd. 1/2" x 1/2" angle iron

Signed by:

Craig W. McVean

Date:

11/29/2012

Surveyor's Michigan License No.:

39088