LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Gladwin (County)	Located In Corr	ner Code #	
1. Public Land Survey	T 18N R 1E I	H3	13
Property Controlling in Section	T R		
Miscellaneous Property in Section	S T R S T R R S T R R R R R R R R R R R		\$
A I sable.			Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G H I J K L M
5. Private Claims:			2 - 6 - 5 - 4 - 3 - 2 - 1
requirements of PA 74, Mir and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	ield survey on June 28, 2010 do hereby stichigan PA of 1970, the corner points menticing mance with regulations and rules therefore vey instructions of the United States Department or by a decree of a Court of Law lines 3, 4 and 5 above were in conformance of Land Surveyors or by a Decree of a Court of Law lines 3, 4 and 5 above were in conformance.	aned in lines 1 as required in artment of the and/or that the with the rules Court of Law:	3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 5 6 - 18 - 17 - 16 - 15 - 14 - 13 - 7 7 8 - 19 - 20 - 21 - 22 - 23 - 24 - 1
	monumented, recovered, found as expresse		9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
			12 3 32 33 34 35 36
			13
A. Description of original monument and accessories and/or subsequent restoration:			
 J. Meyers - Set of N89°31'20"W 2650 3) N35°E 6" Maple 5) S15°W 8" Maple 	L. y – L. 2, p. 334 & Section 11 worksheet apped iron (RLS). S89°31'20"E 2652.24 .60 to 'G3'. 28.65'; 4) N15°W 14" Poplar 17.25' 32.60' y – L. 2, p. 343 – J. Meyers.	l' to 'I-3'.	
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:			
H3 – ¼ Corner common to Section 3 & 10, T18N, R1E – Found ½" x 18" rebar with cap #9433 with coffee can with concrete around it. N GLO evidence was found. ½" CIR fits witnesses #3, 4 & 5. #4 is dead. No evidence of GLO Witnesses. Single strand fence wire goes S & E from ½" CIR. Notes by J. Meyers indicate that this ½" CIR was basically set mid-way and on line between 'G3' and 'I-3' Measured Grid bearing and distance from ½" CIR of S89°15'06"E 2649.84' (2637.36' – GLO, 2652.24' – JM) to 'I-3' and S89°03'26"W 2650.14' (2637.36' – GLO, 2650.60' – JM) to 'G3'. Thus the ½" CIR is 4.5' South of a straight line between 'G3' and 'I-3'. Based on the occupation and monumentation South of this ½" CIR that is based on J. Meyers surveys, I felt it was in the public's best interest to accept the ½" CIR as a locally accepted corner and the best available evidence of the position of the origina corner.			
C. Description of monun	nent for corner and accessories establish	hed to perpetuate lo	ocating the position of the corner:
H3 – Replaced ½" x 18" Set Blue Carsonite N34°E 28.76' to set S12°W 32.81' to set N40°W 12.32' to set	CIR in coffee can and concrete with sta	mped 4" DNR Alum.	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088
Signed by: Surveyor's Michigan	ning W Me Van	Date:	1/26/2012 39088 JAN 39088