

AUG 28 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
Gladwin County Remonumentation

701 PAGE 317

For Corners in

GLADWIN

(County)

Located In:

Corner Code#:

1. Public Land Survey T. 18N R. 2W A-5
- T. \_\_\_\_\_ R. \_\_\_\_\_
- T. \_\_\_\_\_ R. \_\_\_\_\_
2. Public Controlling S. \_\_\_\_\_ T. \_\_\_\_\_ R. \_\_\_\_\_
- in Section S. \_\_\_\_\_ T. \_\_\_\_\_ R. \_\_\_\_\_
3. Miscellaneous S. \_\_\_\_\_ T. \_\_\_\_\_ R. \_\_\_\_\_
- Property in Section S. \_\_\_\_\_ T. \_\_\_\_\_ R. \_\_\_\_\_
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

STATE OF MICHIGAN  
GLADWIN COUNTY  
FILED-REMONUMENTATION

10 AUG 2000 11:22:07 AM

BONNIE K. HOUSE  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on March 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1838 Nicholson--Set Post  
Wit-(1)Maple 11 Sec Cor  
(2)Pine 8 S53W 07

1978 County Road Plans  
Fd Iron, intersection of roads  
Wit-none

1905 Johnson  
Wit-(3)Cedar Post 8' N43 1/2W 67

1988 Lapham--Sec Subd, wkg dwg  
Found 5/8" Iron  
Wit-none

APPROVED LAND CORNER

P.A. 345 of 1990  
Gladwin County

Co. Rep.

Date

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 5/8" x 18" bar 12" below surface in centerline of road intersection. Lapham (1988) measured 2639.59' to A-4 and 2624.13' to L-5, T18N, R3W. Accepted found 5/8" iron as corner of record; replaced with 5/8" x 36" rerod.

See dossier for detailed report on corner A-5.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" rerod with Gladwin Remonumentation cap marked P.S. 27458. Accepted as best available evidence to perpetuate position of corner A-5.

Witnesses:

N45°W, Power Pole, 43.75'

N45°E, Power Pole, 43.65'

East, nail & tag in asphalt road, 77.05'

S45°W, 1/2" x 18" C.I. Witness Iron, 47.85'



Signed by

*Mark R. Robison*

Date

8-9-00

Surveyor's Michigan License No. 27458