

STATE OF MICHIGAN - GLADWIN COUNTY GLADWIN Ann Manning - REGISTER OF DEEDS COUNTY 11/30/2016 1:38 PM RECORDED

Receipt #: 104426 Page: 1 of 2 30.00 CORNEŘ

Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Joshua R. Davidson					Field Survey Date: February 5, 2014		
For corner(s)	in: Gladwin			County			
Original Public Land Survey Corner				Corner Code			
S	1, 2 T	19N R	01W	K2			
s	T	R			ABCDEFGHIJKLM_		
s	Т	R					
S	T	R			$\begin{array}{cccccccccccccccccccccccccccccccccccc$		
Property Controlling Corner				Corner Code			
S	Т	R			_ 5		
S	T	R					
s	T			***************************************			
S	T	R			7 8 19 20 21 22 23 24 8		
Property Corner				Corner Code			
S	T	R			_ 10 _ 30 _ 29 _ 28 _ 27 _ 26 _ 25 _ 10		
S	T	R			11 11		
S	T	R					
s	T	R		****	- 12 31 - 32 - 33 - 34 - 35 - 36 12 - 13 13		
Protracted Public Land Survey Corner				Corner Code	ABCDEFGHIJKLM ¹³		
S	Т	R					
S	Т	R	***************************************		-		
s	T	R			_		
S	Т				-		

Part A: Corner History

K2 - 1/4 corner common to sections 1 & 2, T19N, R1W

- 1877 GLO Resurvey by Merrill set post for 1/4 sec cor 1) dead Hemlock 22" N44°W 20 lks. 2) dead Maple 10" S40°W 26 lks.
- 2002 LCRC Page 497, M. R. Robison, PS #27458 Set Capped Iron by S.P.M. 3) S50°E 56.43' 16" W. Pine; 4) S02°W 46.08' 16" W. Pine; 5) N45°W 61.13' 12" W. Pine; 6) S55°W 20.90' 12" Poplar.
- 2006 LCRC L. C1, P. 760, M. Miles, PS #47965 Set ½" X 24" rerod w/ co. cap #28417 by S.P. 6' East to N-S Fence. -7) N13°E concrete pillar, 47.71'; 8) S43°E 12" Poplar, 20.28'; 9) S18°W 20" W. Pine, 41.34'; 10) N17°W 24" W. Pine, 10.92'.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

K2 - 1/4 corner common to sections 1 & 2, T19N, R1W

No GLO evidence was found. Set a stamped 4" DNR aluminum cap on a 1" X 36" galvanized iron pipe in North-South fence line at prorated distance between section corners 'K1' and 'K3'. The fence line runs North from 'K3' to a concrete pillar. From the concrete pillar the fence line runs East 109' then turns to the North. DNR monument accepted as a careful and faithful reestablishment of the position of the original corner.

- Reference Pt. 'A' N85°02'E 52.41' from 'K2' to Fd. a ½" rebar & cap #27458 per LCRC Page 497. This position was set by single proportion using a rejected position of 'K1' and is not utilized as 'K2' in this survey.
- Reference Pt. 'B' S15°01'W 28.31' from 'K2' to Fd. a ½" rebar & cap #28417 per LCRC liber C1, Page 760. This position was set by single proportion using a rejected position of 'K3' and is not utilized as 'K2' in this survey.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

K2 - 1/4 corner common to sections 1 & 2, T19N, R1W

set a stamped 4" DNR aluminum cap on a 1" X 36" galvanized iron pipe. - Set blue post 1' Northeast.

North 19.08' to Southeast corner concrete pillar S86°E 10.65' to set nail & tag N. side 9" W. Pine N60°W 8.57' to set nail & tag NE. side 8" W. Pine N85°02'E 52.41' to fd. ½" rebar and cap #27458 – Reference Pt. 'A' S15°01'W 28.31' to fd. ½" rebar and cap #28417 – Reference Pt. 'B'

Certifying Surveyor's Name

November 28, 2016

Date

Prepared By: Joshua R. Davidson

Professional Surveyor's License No.:

Department of Natural Resources

8015 Mackinaw Trail Cadillac, MI 49601 JOSHUA R.
DAVIDSON
PROFESSIONAL
SURVEYOR

No. 46659

POFESSIONS

Personanda Pa