

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
GLADWIN

(County)

Located In:

Corner Code #

1. Public Land Survey

T 20N R 2E

B-9, C-8

T R

C-9

T R

T R

2. Property Controlling  
in Section

S 30 T R

2

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, CARL T. KIISKILA, in a field survey on DECEMBER 19, 19 94,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law, established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
B-9 C-8 C-9

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY,  
AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B"  
BELOW.)

B. CONT - THAT SPIKE AT NW  
S-30 THAT THEY USED WAS NOT  
GOOD AND NAIL WE FD AT NW S-30  
WAS BASED ON PREVIOUS SURVEY  
BY RLS, G. HENNING.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-9  
REESTABLISHED THE N 1/4 COR OF  
SEC 30 PRORATED TO THE US  
GOVERNMENT RUN OUT AND ON LINE  
BETWEEN FOUND SECTION CORNERS  
TO E & W. FD 1/2" REROD, 26'  
N'LY, WAS SET IN ERROR BY  
P.LAPHAM IN 1977; IT WAS SET  
BASED ON FD SPIKE AT NW COR OF  
SEC 30 WHICH ALSO WAS NOT  
ACCEPTED THIS SUR. J.MEYERS,  
PS#14099 AN ASSOCIATE OF  
LAPHAM, AGREED -- CONT ABOVE--

C-8  
FOUND AND ACCEPTED A CEMENT  
NAIL FOR THE E 1/4 COR OF  
SEC 19. DISTANCES TO THE SEC  
COR TO THE N & S AGREE WITH  
WORK DONE IN SEC 20 BY G.  
HENNING.

C-9  
FOUND AND ACCEPTED A CEMENT  
NAIL FOR THE NE COR SEC 30  
REPLACED WITH A 1/2" X 18"  
REBAR. COR FITS CERTIFICATE  
SURVEYS IN SECTION 30.

2  
ESTABLISHED THE NE COR OF THE  
NW 1/4 OF THE NE 1/4 SEC 30 BY  
STANDARD PROCEDURES FOR  
SUBDIVISION OF A SECTION.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-9  
SET DNR MON & CED POST.  
4" ASH N77°E 22.79'  
6" ASH S09°E 16.72'  
4" ASH S68°W 23.12'  
15" ASH N45°W 34.84'  
FD 1/2" REROD N04°E 26.08'  
N-W FENCE LINE NORTH 123'

C-8  
FD CUT NAIL IN CTR OF N-S RD,  
REPLACED WITH 5/8"x 16" CAPPED  
REROD.  
14" W PINE N33°W 82.84'  
14" R PINE S60°W 65.23'  
4" W PINE S67°E 55.59'  
11" W PINE N51°E 55.08'

C-9  
FD CEMENT NAIL IN CTR N-S RD,  
REPLACED WITH 1/2"x 18" REROD  
W/CAP.  
COR FN POST N80°W 37.73'  
6" ASH S48°E 46.81'  
4" ASH N84°E 63.78'  
FENCE POST N27°W 63.78'

2  
SET 5/8" X 32" CAPPED REROD &  
CEDAR POST.  
4" ASPEN N78°W 13.53'  
6" ASH N26°W 37.24'  
4" ASH N18°E 53.73'  
7" ASH S13°E 20.30'  
FD 3/4" IR PIPE  
S16°05'E 44.4'

\*OLD WITNESS TO REROD

\*OLD WIT BY OTHERS.

\*OLD WITNESSES

Signed by Carl T Kiiskila Date 1-23-96

Surveyor's Michigan License No. 33981