

NOV 12 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic
(County)

Located in:

Corner Code #

1. Public Land Survey

T 43N R 38W

GH 6-7

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Other
008

Register's Office } ss.
Gogebic County }

Received for record the

27TH day of OCTOBER

A. D. 1997 at 11:15 o'clock

A m., and recorded in

Lib. 6 of CORNERS

on page 252

Ramona Collins Deputy
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Mile Corner #11, Mich-Wisc State Line

I, Gary L. Pisoni, in a field survey on June 26, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847.

Original bearing trees:

Y. Birch	14"	N 85°E	3 links (1.98 feet)
Y. Birch	14"	S 45°W	11 links (7.26 feet)

Corner restored in 1928 by Earl G. Harrington from the two original B.T.s. The yellow birch was standing with the original blaze evident but the marks were burnt out. The birch was a decayed birch stump. He set a standard brass capped concrete monument and two new B.T.s.

Spruce	16"	S 67°45'W	48 links (31.68 feet)
Hemlock	14"	N 32°35'W	117 links (77.22 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the 1928 standard brass capped concrete monument as described in Harrington's notes. The 1928 B.T. is now a decayed hemlock stump and no evidence of Spruce B.T. found.

No evidence remains of the 1847 B.T.s.

Corner Record Research on file with County Representative.

Found bearing trees referencing Mile Corner position:

Sugar Maple	4"	East	17.62 feet
Sugar Maple	9"	S 11°E	35.56 feet
Sugar Maple	6"	N 34°E	15.56 feet
Steel sign post		N 34°E	2.25 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described concrete monument, I established the following:

Sugar Maple	9"	S 45°W	36.24 feet
-------------	----	--------	------------

97-07

Signed by Gary L. Pisoni

Date 7-15-97

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

