

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
Gogebic  
 (County)

Located in: Corner Code #

1. Public Land Survey T44NR41W  
 T R  
 T R  
 T R  
 2. Property Controlling S T R  
 in Section S T R  
 3. Miscellaneous S T R  
 Property in Sec. S T R

South MC I-6-7  
020  
**SURVEY &  
 REMONUMENTATION**  
**JAN 05 2001**  
**SECTION**

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_  
 South Meander Corner common to Sections 14 and 15 on the North  
 Shore of East Bay Lake.

*z p.d.*

I, John R. Garske, in a field survey on ~~December 20, 2000~~ <sup>NOVEMBER</sup>, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and / or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	10			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

**A. Description of original monument and accessories and / or subsequent restoration:**

Original survey by Algernon Merryweather in June - July 1852.  
 Original corner: Cedar 12" diameter corner tree at 62.66 chains South  
 Original bearing tree: Cedar 7" diameter bears N 60°W a distance of 8 links.  
 1981 survey by Genisot Associates.

*DEED GROUP APPROVED*  
*Richard P. Drenth 11/29/00*  
**COUNTY REGISTER**

**B. Description of corner evidence found and / or method applied in restoring or re-establishing corner:**

I found a 1" iron pipe as shown on the 1981 survey by Genisot Associates. Distances check relatively close with map dimensions. Record research on file.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

I accepted the 1" iron pipe and replaced it with a stamped standard aluminum Bernsten monument with 4 foot aluminum rod approximately 30 feet South of the shoreline of Poor Lake. I established the following witnesses:

6' Steel Sign Post	N 37° E	2.01 Feet
10" White Pine	N 70° W	19.77 Feet
6" Tamarack	S 31° W	36.58 Feet
6" Tamarack	S 28° E	22.77 Feet

Signed by John R. Garske

Surveyor's Michigan License No. 28410  
 FB # 230, page 74

Date 11-28-00

