

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office } ss.
Gogebic county }

For corners in

Gogebic
(County)

Located In:

Corner Code #

1. Public Land Survey

T 45N R 41W
T R
T R

L-M, 3-
002

2. Property Controlling
in Section

PEER GROUP Approved
S T R
S T R
S Richard P. Pisoni 5/25/94
S T R

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

Received for record the
1st day of June
A. D. 1994 at 1:45 o'clock
P m., and recorded in
Liber 5 of CORNERS
on page 71
Richard J. Brown
Register of Deeds
Register of Deeds Stamp & File Number

East Meander Corner between Sections 1 and 12.

I, Gary L. Pisoni, in a field survey on December 1, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therofore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Algernon Merryweather, U.S. Deputy Surveyor on June 9, 1852.
Original corner: 8" cedar corner tree.
Original Bearing tree:
Balsam 4" S 80°E 15 links (9.90 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner evidence found. Restore corner position on the East shore of Beatons Lake and on line between the West Meander Corner and the Southeast corner of Section 1.
Monument located 14 feet from waters edge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I set a 2" diameter by 30" long split base aluminum pipe monument with a 3" cast aluminum cap, stamped to read: T45N, R41W, M.C., S-1, S-12, 1993, RLS- 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Hemlock	12"	N 53°E	42.75 feet
Hemlock	4"	S 22°W	12.14 feet
Cedar	5"	S 65°W	20.90 feet
Steel Sign Post		East	1.20 feet



Signed by Gary L. Pisoni
Surveyor's Michigan License No. 27457

Date 4-1-94