

# SURVEY & REMONUMENTATION

AUG 8 1997

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic  
(County)

Located In:

Corner Code #/

1. Public Land Survey T 45N R 46W
2. Property Controlling S      T      R
3. Miscellaneous S      T      R
- Property in Sec. S      T      R

LM

~~3-4~~

001

Register's Office } ss.  
Gogebic County }

Received for record the  
11<sup>th</sup> day of JUNE

A. D. 1997 at 10:45 o'clock

A m., and recorded in

Lib. 6 of CORNERS

on page 150

Colleen M. Kibak, Deputy  
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No.     , Recorded Plat
5. Private Claims

Mile Corner #6, Mich.---Wisc. State Line

I, Richard L. Drahn in a field survey on May 26, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

### A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847. Original B.T.s---Hemlock 16" N.63 E. 36 links (23.76)--- Hemlock 7" S.33 W. 5 links (3.30') ---

Corner restored in 1928 by Earl G. Harrington from the stump remains of the two original B.T.s. He set a standard brass capped concrete monument and two new B.T.s : --- Cedar 14" N.03 W. 18.8 ft. --- Maple 10" S.58-30 W. 3.3 ft. ---

Research form on file with Gogebic County records.

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the 1928 standard brass capped concrete monument as described in Harringtons notes. His B.T. at N.03 W. is now a 14-16" decayed Cedar windfall. His B.T. at S.58-30 W. is now a live 15" Red Maple with 1928 blaze grown over.

A Hemlock stump at N.63 E. and a stump hole with fragments of decayed Hemlock wood and bark still remain from Burts 1847 B.T.s.

PEER GROUP APPROVED

Richard L. Drahn 6/10/97  
COUNTY REPRESENTATIVE

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described concrete monument I established the following:

- |     |                 |         |           |
|-----|-----------------|---------|-----------|
| 4"  | Sugar Maple     | N.39 W. | 22.46 ft. |
| 5"  | Sugar Maple     | N.77 E. | 42.91 ft. |
| 10" | Sugar Maple     | N.28 E. | 12.60 ft. |
| 6'  | Steel sign rail | N.26 E. | 2.55 ft.  |



Signed by Richard L. Drahn

Date June 5, 1997

Surveyor's Michigan License No. 21564