

AUG 0 8 1997

COMMISSIONIN

expressed below:

on this certificate.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Gogebic	Office	~~
Gogebic	County	388

	Recei	ved for	19001	l tha
	674	day of	JUL	<i>y</i>
A. D.	19 <u>.9.7</u> .	at/-	40 0'	CICCK
	<i>P</i> n			
	6			
cy, po	leen suty	'	. 1	.0 0
Cal	lun	m	Bu	chak
Dex	autu	Regist	er of	Decis

For corners in		t ming to quite extended by		day of July
	Gogebic (County)	Located In:	Corner Code ##	A. D. 19 97. at 1:40 o'clock P. m., and recorded to
1.	Public Land Survey	T 45N R 46W	HI-2-3	Liber 6 of CORNERS
		T R T R T R	007	Collein Kichek
2.	Property Controlling in Section	S T R S T R		Deputy Register of Doods
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4.	Lot No,	Recorded Plat		B C D E F G H I J K L M
5.	Private Claims			2 6 5 3 2
	Mile Corner	No. 4; MichWi	sc. State Line	3 4 7 8 9 10 11 6/125
do in cu	hereby certify that under re lines 1 and 2 above were i grent manual of survey inst	in a field survey on	A. of 1970, the corner points mention and rules therefore as required in t artment of the Interior, Bureau of La	ed 6 18 17 16 15 14 13 nd 7
Ma ab	anagement or by a decree of love were in conformance w	of a Court of Law and/or that the corr with the rules of the Michigan Board	ner points mentioned in lines 3, 4 an Fof Land Surveyors or by a Decree c	d 5 8 19 20 21 22 23 24 of a 9

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Corner established by William Burt in 1847. Original B.T.s --- Hemlock 7" N.74 E. 66 links (43.56') --- Cedar 8" S.76 W. 18 links (11.88') ---

Corner restored by Earl Harrington in 1928 from the original (18") scribed Cedar B.T. He set a standard State Line concrete, brass capped monument and established two new B.T.s. --- Cedar 18" North 8.6 ft. --- Cedar 15" S.49-30 E. 7.3 ft. ---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the standard brass capped concrete monument as described in Earl Harringtons notes. His B.T. North 8.6' is now a 19" Cedar windfall with scribing visible. His B.T. at S.49-30 E. is now a large badly decayed Cedar windfall.

William Burts Cedar B.T. is now a downed, badly decayed Cedar. evidence remains of his Hemlock B.T.

Research Form on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the above described concrete monument I established the following new bearing objects:

8"	Red Maple	N.63 W.	21.72	feet
9"	Sugar Maple	N.29 E.	25.09	feet
7"	Red Maple	s.27 W.	9.05	feet

Steel sign rail N.16 E. 2.24 feet

BI MICH RICHARD L. DRAHN LAND SURVEYOR No. 21564 LAND

Signed by R Surveyor's Michigan License No. 21564 ____Date ___<u>July 3, 1997</u>