BUHVEY & REMONUMENTATION

NOV 1 2 1997

COMMISSION

Property in Sec.

. Lot No. .

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office Gogebic County

Received for re	
9th day of Oc	70841
A. D. 19 97 at 10:50	_o'clock
Am., and rec	orded in
Liber 6 of Co	
Ramona Collins, T Register	
Ramona Collins, I	Deputy
Register (of Deeds

Register of Deeds Stamp & File Number

AAICH,

For corners in Gogebic (County) Corner Code ## Located In: BC-13 001 T46N_ R 46W . Public Land Survey R. (T45N_ R 46W Property Controlling S. __ T _ R in Section S __ T _ _ R . Miscellaneous

. Private Claims _ State Closing Corner Sec's 31 & 6; T.45-46 N., R.46W. Line

_ , Recorded Plat

R

Richard L. Drahn in a field survey on October 2. ∎o hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned au lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land ■anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Sourt of Law; established, re-established, monumented, re-monumented, recovered, found as -xpressed below:

≟OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Corner established by John Burt on August 31, 1847. Original B.T.s --- Hemlock 22" N.49 E. 40 links (26.40') --- Y. Birch 18" N.49 W. 25 links (16.50') ---

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record distance from Mile Corner No. $\frac{1}{2}$ and record bearing and distance from the decayed remains of the two original bearing trees. The first is a series of root holes with fragments of Hemlock wood and bark. The second one is now a series of root holes with decayed fragments of Yellow Birch bark and wood.

Research form on file with Gogebic County records.

REPRESENTATIVA

11

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2" X 30" aluminum pipe with a $3\frac{1}{4}$ " aluminum cap stamped to indicate the corner position and the following new B.T.

15"	Hemlock	s.28 W.	8.351
14"	Hemlock	s.47 E.	30.30'
4"	Red Maple	s.70 E.	9.41'
6 '	Steel sign rail	N.18 E.	1.97'

_ Date <u>October 6,</u>

urveyor's Michigan License No. 21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

REVISED JAN., 1983

01 A1CH

RICHARD L. DŘAHN LAND SURVEYOR 21564

FED LAND