

NOV 1 2 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office }
Gogebic County } ss.

For corners in

Gogebic

(County)

Located In:

Corner Code #

1. Public Land Survey

T47NR 44W

B-11

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

Received for record the
18th day of SEPTEMBER

A. D. 1997 at 10:45 o'clock

A m., and recorded in

Liber 6 of CORNERS

page 194

Ramona Collins, Deputy
Register of Deeds

Register of Deeds Stamp & File Number

I, John P. Goss, in a field survey on Sept. 4, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1/4 cor. comm. to sec's. 30 & 31

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William Burt in 1848.

Original bearing trees: Hemlock 8" N 10° E 18 links
Hemlock 12" S 05° W 22 links

On September 30, 1970, Donald D. Lappala, RLS, restored corner position at record bearing and distance from the remains of the two original bearing trees. One was a large decayed windwall and the other is now a decayed hemlock stump. Corner position verified further by measurement of 6.00 chain East from corner to a Sugar Maple 12" (now decayed sugar maple stump). He set a 2 1/2" iron pipe with 3" bronze cap which indicated the corner position. He established the following

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

bearing trees: 4" S. Maple - S 53° E - 20.3'; 4" S. Maple - S 16° W - 28.4';
6" R. Maple - S 88° W - 23.5'.

Corner recorded in USFS Liber V-3, on August 10, 1972.

Found Donald D. Lappala corner monument and witnesses.

I Updated the corner monument and accessories as noted below to state and county specification.

Act 74 research on file.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the 2 1/2" iron pipe with 3" Bronze cap which reads: T.47 N., R.44 W.; 1/4; S-30, S-31; R.L.S. 12585; 1970, from which I established existing and new bearing trees and new reference object.

6" Sugar Maple S 53° E 20.35'
7" Sugar Maple S 16° W 28.30'
8" Red Maple S 88° W 23.50'
9" Sugar Maple N 30° E 7.10'
6" Rail & sign Due East 1.90' (to face)

(All measurement to nail in side of tree)

PEER GROUP APPROVED

Richard L. Dean 9/17/97
COUNTY REPRESENTATIVE



Signed by John P. Goss

Date September 4, 1997

Surveyor's Michigan License No. 23509

Fed. No. V-3