LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74. Mich. PA 1970

	i mig reduitorie of receive, a	
For Corners In: Grand Traverse (County)	Located in Corner Code #	
1. Public Land Survey	T 26N R 10W J11	
Property Controlling in Section	S T R S T R	
Miscellaneous Property in Section	S T R S T R	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	ABCDEFGHIJKLM
5. Private Claims: _		2 - 6 - 5 - 4 - 3 - 2 - 1
requirements of PA 74, Mi and 2 above were in conforthe current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established	eld survey on November 5, 2009 do hereby state that under chigan PA of 1970, the corner points mentioned in lines 1 ormance with regulations and rules therefore as required in rvey instructions of the United States Department of the anagement or by a decree of a Court of Law and/or that the clines 3, 4 and 5 above were in conformance with the rules of Land Surveyors or by a Decree of a Court of Law; I, monumented, recovered, found as expressed below: 2 corners, all in the same town and range, may entificate.	3 4
		13
A. Description of original monument and accessories and/or subsequent restoration: J11 - 1852 - GLO - L. S. Scranton - set Beech Post for qr. sec. corner, 1) Sugar 15" S35°W 39; 2) Beech 10" N6°E 37 - 1917 - CSR-Liber 3, Page 374 - E. P. Waterman - Cor. #14 has one US wit. standing - the 2) beech 10 N6°E 37 lks We found the old stake hole perfect, made new wit. By 3) Beech 12" S10°W 18.5'. Owners of these lands promise to drive iron stake at all corner's marked by small circle 1933 - M. Schaaf index - Corner set by measurement 1978 - unrecorded Property Sketch - J.L. Wilcox & associates file #78275 - 1½" iron pipe found - 4) N20°E 22.15' - 8" Maple, 5) S65°E 25.03' - 6" Maple, 6) N45°W 24.34' -5" Maple 1988 - LCRC L. 3, P. 124 - Neil Livasy, PS #31611 - Found 2" iron pipe, at intersection of old fencelines to North, South, East & West, at NE Corner of oil well drilling pad 7) 4" Ironwood - S44°E 7.35, 5) 8" Maple - S69°E 25.00', 6) 6" Maple - N45°W 24.35', 4) 6" Maple - N21°E 22.08' 2001 - Certificate of Survey L.9, P.257-261 - Phillip D. Case, PS #30079 - 2" Iron Pipe. Wits. same as LCRC L.3, P.124. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: J11 - Quarter Corner common to sections 26 & 35, T26N, R10W - Found 1¾" X 36" long iron pipe and witnesses #4, #5, #6 & #7, fitting position. Fence remains W & S. Witnesses 1, 2, & 3 are gone. Found 1¾" X 36" iron pipe accepted as a careful and faithful perpetuation of the position of the original corner.		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: J11 - Replaced 1¾" X 36" iron pipe with a stamped 3 ¼" Grand Traverse Co. Remon. Brass Cap on 2 ½" x 30" galv. iron pipe with a ring of stones. Set orange carsonite post 1' North N21°E 22.06' to fd. 60d nail in SE side 11 Sugar Maple (#4) S68°E 25.04' to fd. 60d nail in N side 10" Sugar Maple (#5) S50°E 7.32' to fd. nail NE side 6" Ironwood (#7) N45°W 24.40' to set nail & tag at old nail in NE side 9" Sugar Maple (#6) CRAIG W. MCVEAN PROFESSIONAL SURVEYOR NO. 39088		
Signed by: Surveyor's Michigan	License No.: 39088	: 1/6/2011 TOPESSIONAL