## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

| For Corners In:<br>Grand Traverse<br>(County)  | Located In  | Corner Code #  |  |
|--|---|--|--|
| 1. Public Land Survey  | T 26N R 10W   | K9   |  |
| Property Controlling in Section  | T R<br>S T R  |  |  |
| Miscellaneous     Property in Section  | S T R S T R R S T R R   |  | Register of Deeds Stamp & File Number  |
| 4. Lot No:   | Recorded Plat:  |  |  |
| 5. Private Claims:   |   |  | A B C D E F G H i J K L M  |
| requirements of PA 74, Mic<br>and 2 above were in confor<br>the current manual of sun<br>Interior, Bureau of Land Ma<br>corner points mentioned in<br>of the Michigan Board of   | eld survey on November 4, 2009 do he chigan PA of 1970, the corner points mance with regulations and rules the vey instructions of the United States nagement or by a decree of a Court of lines 3, 4 and 5 above were in conformation of Land Surveyors or by a Decree of monumented, recovered, found as ex | mentioned in lines 1 refore as required in s Department of the f Law and/or that the mance with the rules of a Court of Law; | 3 4  |
| NOTE: Not more than 2 corners, all in the same town and range, may   |   |  | 9 10 30 29 28 27 26 25   |
| be recorded on this certificate.   |   | 11   |  |
|  |   |  | 12 31 32 33 34 35 36   |
| A. Description of original   | monument and accessories and/o  | or subsequent restoration  |  |
| <ul> <li>- 1963 – DNR Land Corner Record – K.J. Ostling – This corner was established while making a survey of Section 25. Set corner at intersection of road centerlines N-E-W. This conforms to U.S. measurement to section corner East and probably replaces any previous established corner which obviously was removed in road construction. Nothing for USBTS. – Drove 1" X 36" pipe in road intersection, 3) 10" R. Pine N35°W 58.2', 4) 12" W. Oak N53°E 70.4'.</li> <li>- 1973 – LCRC L. 1, P. 733 – Larry Gerschbacher, PS #18990 – Found ¾" iron pipe 5) 6" W. Oak N43°W 63.14', 3) 12" R. Pine N36°W 58.50', 6) 9" J. Pine S66°E 36.43', 4) 15" R. Oak N45°E 71.10'.</li> <li>- 1978 – J. L. Wilcox – Property Sketch, file No. 78-275 – DNR Monument found 3) 10" R. Pine N35°W 58.2', 4) 12" W. Oak N53°E 70.4'.</li> <li>- 1981 – Certificate of Survey L. 3, P. 954 – Wm. B. Batzer, PS #13026 – Found ¾" iron pipe 3) N30°W 58.43' - 16" R. Pine, 7) S50°W 54.22' – 8" Maple, 8) S30°E 61.20' – 6" Maple.</li> <li>B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:</li> <li>K9 – Corner common to sections 23, 24, 25 &amp; 26, T26N, R10W - Found Schaaf monument- short 1" x 7" long iron pipe in 6" X 6" X 4" block of concrete- 1.1' below grade in centerline East-West gravel road and 3'± West of centerline 2-track to North. Also found 1" x 42" long iron pipe as set by Ostling and used by Gerschbacher, Wilcox &amp; Batzer is S62°27'E 1.59' from 'K9' (Schaaf monument). Removed Ostling's 1" pipe and replaced with ½" X 18" rebar- 1.4' below grade. Found Schaaf 1" pipe in 6" X 6" X 4" block of concrete accepted as a careful and faithful perpetuation of the original corner.</li> </ul> |   |  |  |
| K9 – Lowered 1" pipe in<br>2 ½" x 30" galv. iro<br>Set Blue Carsonite<br>N50°E 71.58' to se<br>S62°E 1.59' to ½"   | n pipe - 0.6' below grade.  | placed above it a stampe<br>8" Twin W. Oak (#4)  | ocating the position of the corner:  led 3 ½" Grand Traverse Co. Remon. Brass Cap on |
| \$35°W 62.76' to for<br>\$51°W 53.66' to for<br>\$34°W 57.21' to so  | I. 60D nail in NW side 9" W. Oak I. 60D nail in NW side 9" W. Oak I. 60D nail in NW side 10" Twin R. et nail & tag in NE side 16" R. Pine   | Maple (#7)<br>e (#3)   | CRAIG W. McVEAN PROFESSIONAL SURVEYOR No. 39088                                      |