LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. PA 1970

	Filing Requirement of Act 74, Mic	ch. PA 1970
For Corners In: Grand Traverse (County)	Located In Corner Code #	
Public Land Survey Property Controlling in Section	T 27N R 9W E-9 T R	
Miscellaneous Property in Section	S T R S T R S T R S T R S T R S T R S T R S T R S T T R S T	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	•
5. Private Claims:		1 A B C D E F G H I J K L M 2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
I, <u>Craig W. McVean</u> , in a field survey on <u>Oct. 21</u> , 1999 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		3 4
NOTE: Not more than 2 be recorded on this cer	2 corners, all in the same town and range, may rtificate.	10 30 29 28 27 28 25 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:		
 MDNR corner Rec. set Std. Dept. Mon section corner W, s 	24 L., Y. Pine 18" N35°E 80 L. R.A. Rad found corner + Y. Pine 18" N35°E 84 L. – C.F Roser –1968 by double Prop. between ¼ corner N, ection corner S, & ¼ corner E. haaf notes to USBT- Y. Pine stp. N35°E 7" Oak S46°E 15.8', 3°E 26.7', 9" Tw. Oak S72°W 14.8', V. 2', C/L fire lane E. is N. 8',	Sportsman's' Park L.11 of plats pg. 3-7- Jemaker –1972 - concrete monument placed.
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:		
Fits plat of 'Sportsm DNR monument is 3	nmon to section 20, 21, 28&29 – Found DNR monument nan's' Park, no concrete monument apparently placed. Y 3' West of CL. N-S firelane and 5' South of centerline Fire cepted as a careful & faithful reestablishment of the posit	∕. Pine stump to Northeast is gone now. elane E.
C. Description of monume	ent for corner and accessories established to perpetuate	locating the position of the corner:
Galvanized iron pipe S67°W 15.24' to S32°E 50.32' to N44°W 36.43' to N68°E 109.96' to	Alum. Cap on 1" X 3' long iron pipe with 3 ¼ " 'Grand Tra e – down 0.7' set N&T in S. side Tw. 18" R. Oak (CFR) set N&T in SW side 9" W. Oak scribed 'XBT' set N&T in NE side 5" R. Oak scribed 'XBT' set N&T in N side 8" W. Pine scribed 'XBT' et blue carsonite post with location tag & found cedar with	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No.
Signed by: Surveyor's Michigan Li	raie W. Mullen Date: icense No.: 39088	12/13/1999 P. 39088 SEESSION S