LIBEROO2 PAGE 151

01/08/97

MAY 1 6 1897

COMMISSION

COMMAND Filing Requirement of	of Act 74, Mich. P.A. 11970 and Reg of Deeds 2:24 pm
For corners in	BJK Fee: 9.00
Leelanau Located In: C	Corner Code # 04B00002 P0151 Page 1 of 1
	<u>C-5</u>
T R	#454
<u>T</u> R	
	leelanau Reg of Deeds 2:24 FM
Property in Section S T R	04B00002 P0151 Page 1 of 1 Register of Deeds Stamp & File Number
•	
4. Lot No, Recorded Plat	
5. Private Claims	2 6 - 5 - 4 3 - 2 - 1 -
	3
	4
i, Steven P. Bye , in a field survey on October 24	, 19_96, 5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970	
in lines 1 and 2 above were in conformance with regulations and rules there manual of survey instructions of the United States Department of the	
Management or by a decree of a Court of Law and/or that the comer point	ts mentioned in lines 3, 4 and 8 19 20 21 22 23 24
5 above were in conformance with the rules of the Michigan Board of Pr Decree of a Court of Law; established, re-established, monumented, re-management	
as expressed below:	10 30 29 28 27 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, n	nay be recorded
on this certificate.	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or su	hsequent restoration:
C-5: Southwest corner Section 8	boequent restoration:
G.L.O. notes	
"Set post corner to Sections 7, 8, 17,	& 18."
Witnesses:	
Sugar 16 N5°W 22 links	
Do. 16 S17°E 17 links	
Stone with "X" found in 1972 by Batzer Witnesses: N 9 & 20.34 4 Maple	y .
N 79½°W 16.69' 8" Maple	
S 29 3/4°W 8.54' 12" Maple B. Description of corner evidence found and/or method applied	in restoring or reestablishing corner:
C-5: Southwest corner Section 8	
Stone with "X" found in 1972 by W. Batz	er.
Witnesses:	
N 9 1/4° E 20.34' 4" Maple N 79 1/2° W 16.69' 8" Maple	APPROVED LAND CORNER
S 29 3/4° W 8.54' 12" Maple	P.A. 345 OF 1990
0 25 574 " 0.54 12 Hapte	LEELANAU COUNTY
	DATE: 10-23-96
	COUNTY REP. MM. O'Non
	COUNTY HEP. PETER TO TEST
C. Description of monument for corner and accessories establish	shed to perpetuate locating the position of the corner:
C-5: Southwest corner Section 8	· · ·
	s a careful and faithful reestablishment of the
Crown October 23 1996 and replaced to	Leelanau County Remonumentation Peer Review with a 3/4" i.d. galvanized iron pipe 31-long
with a brass cap and protective monumer	at box.
Existing Witnesses:	Set New witnesses:
4" Maple N9°E 20.34"	8" Maple S/9"W 16.69"
12" Maple S29°W 8.54'	4" Maple N9 E 20./0'
	24" Bass N24°W 13.14'
	No.
<i>(</i> /,	35991
Signad by Steer O. R.	Day 12 12 1/21
Signed by // Neven P. Dye	Date /2/26/96
Surveyor's Michigan License No. 35991	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

LAND CORNER RECORDATION CERTIFICATE are Kirt