

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: See below

For corner(s) in: Baraga County

Original Public Land Survey Corner

Corner Code

a. S T 49N R 33W K08 (GCDB 600340)  
b. S T 49N R 33W L09 (GCDB 640300)  
S T R  
S T R

Property Corner

1/16 Corner Code

S T R  
S T R  
S T R  
S T R



	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) Quarter corner common to Sections 23 and 24. 1852 - Established by Z.B.Searles, Deputy, midway and on the Section line between Section corners 39.97 chains north and south. Set post. Sugar 12" N29°E 24 links, Sugar 14" S60°W 28 links. Found no subsequent record.

b.) Quarter corner common to Sections 24 and 25. 1852 - Established by Z.B.Searles, Deputy, midway and on the Section line between Section corners 40.375 chains east and west. Set post. Y.Birch 8" S18°W 5 links, Spruce 6" N22°E 4 links. 1946 - Norman T. Thompson, RLS, states "OBT spruce 6" N22°E 2.6' down. Set ced. post. New BT Sugar 10" N54°W 39.4', New BT Maple 5" N14°E 15.4'. Well-blazed old line east.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Sept. 27, 2017. The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2626.15' north and south.

b.) Oct. 4, 2017. The original post and accessories were not recovered. Could find no remaining evidence of the Thompson 1946 retracement and was forced to conclude that the corner is now lost. Therefore, I reestablished the position for the corner midway and on the Section line between Section corners 2672.89' east and west.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
6" Sugar N67°E 18.6' mrkd "1/4S NBT"  
10" W.Spruce S52°E 26.75' do  
10" Sugar S74°W 9.1' do  
10" Sugar N37°W 24.2' do  
Set sq'd cedar post adjacent.  
E= 7893822.062 N= 206046.141

b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap Set measuring nail with MDNR tag in the side of:  
9" Sugar N44°E 7.0' mrkd "1/4S NBT"  
11" Sugar N87°E 12.8' do  
13" Hemlock S25°W 10.75' do  
4" Sugar S83°W 27.65' do  
Set sq'd cedar post adjacent.  
E= 7894615.221 N= 205222.737

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID RL0041: N= 210246.994 m. E= 7895426.985 m.

Stephan J. Szyszkoski 10/16/2017