

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Houghton

(County)

Located In:

Corner Code #

1. Public Land Survey

T 51N R 35W

F8

T R

T R

T R

2. Property Controlling
in Section

S 21 T 51N R 35W

8

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

8 Feb 19 1999

F8 Jan 27 1999

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(F8) Center of Section 21. Corner not established in the original survey. Found no subsequent record.

(8-Sec. 21) West 1/16 corner, Section 21. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F8) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite quarter corners. Placed a 1" IDx32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped, at the corner position.

(8-Sec. 21) Found no evidence of prior monumentation at the corner position. Established the corner on a straight line between Quarter corner 1316.06' West and Center of Section 1316.06' East. At the corner position, placed a 1" IDx32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. Found a forester's approximate corner post #16E 22'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F8) Set 1" pipe with 4" MDNR cap.

(8) Set 1" pipe with 4" MDNR cap.

Blazed and scribed the following:

Blazed and scribed the following:

6" Maple N06E 6.2' "C1/4 BT"

7" Y. Birch N56E 19.35' "1/16S 8T"

8" Sugar N73E 12.5' do

7" Maple N47W 25.1' do

18" R. Oak S23W 25.4' do

8" Sugar S41W 20.7' do

11" Sugar S73W 8.5' do

4" Sugar S27E 33.05' do

Placed a squared sugar post adjacent.

Placed a squared cedar post adjacent.


Bearings are magnetic. Distances are

Bearings are magnetic. Distances are

horizontal and to the notch in lower

horizontal and to notch in lower blaze.

blaze.



Signed by

Stephan J. Szyszkoski

Date

8/26/99

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Forest Management Division