

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton  
(County)

Located In:

Corner Code #

1. Public Land Survey T 51W R 35N 18  
T      R       
T      R       
S      T      R       
2. Property Controlling S      T      R       
in Section S      T      R       
3. Miscellaneous S      T      R       
Property in Sec. S      T      R       
4. Lot No.         , Recorded Plat           
5. Private Claims

Register of Deeds Stamp & File  
Number

Apr 20 2006

I, Stephan J. Szyszkoski, in a field survey on         , 20      do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(18) Quarter corner common to Sections 22 and 23. 1848 - Established by S.W. Higgins, Deputy Surveyor midway and on line between Section corners 40.00 chains north and south. Set post. Bearing trees: Hemlock 10 S65E 18 links, Cedar 10 N25W 4 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(18) The original post and accessories were not recovered. Found a 1" ID iron pipe with 4" aluminum Michigan Dept. of Conservation tablet, stamped to identify the corner, in good condition. Found no evidence of new bearing trees. The monument is located 1.31' North and 0.63' East of the midway position proportionate to the original record between Section corners 2641.70' north and 2644.32' south. This monument was likely placed in 1966 by Billy D. Buckler RLS, but I found no record of this monument in the Michigan Dept. of Natural Resources survey files. Accepted the monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(18) Found 1" ID I. pipe with 4" alum. MI  
Dept. of Conservation cap. Set  
measuring nails in:  
5" Y. Birch East 40.8' mrd "1/4S NBT"  
8" Maple in clump S50W 6.1' do  
5" B.Ash N51W 19.4' do  
6" B.Ash N06W 23.2' do  
Bearings are magnetic. Distances are to  
nail with tag. Sq'd a 3" B.Ash North  
2.7' | 6' long metal fence post adjacent.



Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/2/06

For the Michigan Department of Natural Resources, Office of Land and Facilities