LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

Houghton	Located In:		Corner	Corner Code #									
(County)													
1. Public Land Survey	T 51N T 51N T			3									
2. Property Controlling	s T	-R $-$		1.00									
in Section	s — T —	R											
	s T	${R}-$											
3. Miscellaneous	s — T —	${R}-$		1-1-1-2									
Property in Sec.	STT	R	. 		<u> </u>								
						Regis	ter of C	Deeds	Stam	ρ&Fil	le Nun	nber	
4. Lot No. , Re	ecorded Plat					В	Ср	E	F G	н	1 3	— 7 к	L.
Private Claims					¹ Г	T	П	T	ŤŤ				Ť
	ž.	13	03/07/2008		2	6 	 	\top	-1-	— 3 – 1	十		-1-
ı, Stephan J. Szyszkoski ,	in a field survey on	J3	03/07/2008	do hereby state	3			工	ا و	_10-			_ _12_
that under requirements of P.A.							LĬ		Ĺ	1			Ī
above were in conformance with	regulations and rules th	erefore as	required in the cur	rent manual of survey	y " [1		T					
instructions of the United States	Department of the Inte	rior. Burea	au of Land Managem	ent or by a decree o	16 ├─	-1,8	 1,7		-1,6	1,5	1		1,3

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

re-established, monumented, recovered, found as expressed below:

a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, g

(I3) Corner common to Sections 2-3-10-11. 1969 - Reestablished by A.O.Enger RLS by double proportionate measurement to the original record between section corners 1 mile N, 1 mile S, 1 mile E, and 2 miles W. Set 1"IDx36" I.pipe with 4" aluminum cap. Sugar Maple 7 S30E 73 links, Red Maple 4 S19W 26 links, Balsam 7 N13W 42.5 links.

10

(J3) Quarter corner common to Sections 2 and 11. 1969 - Corner reestablished by A.O.Enger RLS, midway and on line between Section corners 39.84 chains to east and west. Set 1"IDx36" I.pipe with 4" aluminum cap. Red Maple 5 N85 1/2W 25.5 links, Red Maple 4 N88E 9.5 links, Aspen 6 N57E 25.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I3) Found the 1969 monument in good condition and at record bearing and distance from the remaining NBTs Sugar Maple SE and Red Maple SW, both in good condition with overgrown blazes. The Balsam NBT was not recovered. The position of the monument is S32E 10.7' from the double proportionate position as I calculate it from my measurements to the Section corner control noted in Section A, above. I accept the monument as a careful and faithful reestablishment of the position of the original corner.

(J3) Found the 1969 monument in good condition and at record bearing and distance from the Red Maple NBTs. The Red Maple NBT NW is standing dead. Any evidence of the Aspen NBT was obscured by snow cover. My measurements show the monument to be located 5.0' East and 0.3' North of the midway position of record and I accept same as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J3) Found 1"ID I.pipe with 4" alum. MDNR cap. (I3) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 4" Maple S89E 6.1' old blazes (1969 NBT) old blazes (1969 NBT) 8" Sugar S37E 48.7' mrkd "1/4S NBT" 4" Maple S33W 8.1' 7" Maple S23W 17.3' do do 6" Maple S81W 18.6' do 7" Maple N72E 10.0' mrkd "S2 NBT" 3" Sugar N43W 10.8' do "S10 NBT" 5" Sugar S59W 9.8' Set sq'd spruce post adjacent. Bearings magnetic. Set sq'd post adjacent. Bearings magnetic.

33986 Surveyor's Michigan License No.

Date

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOAL

SURVEYOR 4, 1975 CAND sed Jan., 1983

STEPHAN J

SZYSZKOSKI LAND

16037 16038

Rervised Oct., 1995