

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 36W	E8
	T 51N R 36W	G8
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on E8 05/22/2012 do hereby state
G8 05/22/2012
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E8) Quarter corner common to Sections 20-21. 1848 - Established by S.W.Higgins Deputy Surveyor
midway and on the Section line between Section corners 40.00 ch. north and south. Set post. Hemlock
20" N55E 11 links, Maple 12" N50W 19 links. Found no subsequent record.

(G8) Quarter corner common to Sections 21-22. 1848 - Established by S.W.Higgins Deputy Surveyor
midway and on the Section line between Section corners 40.00 ch. north and south. Set post. Sugar
14" N05E 26 links, Balsam 12" N20W 17 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E8) The original post and accessories were not recovered. Found no evidence of the position of the
original corner on the ground. Reestablished the position for the corner midway and on the Section
line between Section corners 2614.24' north and south.

(G8) The original post and accessories were not recovered. Found no evidence of the position of the
original corner on the ground. Reestablished the position for the corner midway and on the section
line between Section corners 2627.39' north and south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Maple N37E 7.15' mrkd "1/4S NBT"
7" Y.Birch S49E 5.2' do
6" Maple S72W 16.2' do
5" W.Spruce N79W 11.75' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(G8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Sugar N72E 7.1' mrkd "1/4S NBT"
5" Sugar S35E 17.25' do
4" Sugar S72W 12.7' do
4" Sugar N53W 14.6' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/11/2012

For the Michigan Department of Natural Resources, Forest Resources Division

