

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Houghton

(County)

Located In:

Corner Code #

**1. Public Land Survey**

T 52N R 35W

J8

T 52N R 35W

M8

T R

T R

**2. Property Controlling in Section**

S

T R

S

T R

**3. Miscellaneous**

S

T R

Property in Sec.

S

T R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Sep 25 2000

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

(J8) Center of Section 23. Not established in the original survey.

(M8) Quarter corner common to Section 24 T52N-R35W and Section 19 T52N-R34W. Reestablished and recorded in 1972 by A.O. Enger, RLS. 1" ID x 36" iron pipe with 4" aluminum cap. W.Spruce 7 S89W 14.4', W.Spruce 5 S89 1/2W 19.9'.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(J8) Established the corner at the intersection of straight lines connecting opposite 1/4 corner corners.

(M8) Found the 1972 monument in good condition and at record bearing and distance from the 1972 witnesses. The SW NBT is a 1' tall stump with blaze visible. The SE NBT is in good condition. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(J8) Set 1" ID x 32" IP with 4" aluminum

MDNR cap. Blazed and scribed:

6" Y. Birch N13.5E 30.6' "C1/4 BT"

6" Sugar N88.5E 26.5' do

8" Sugar S18W 20.1' do

5" W.Spruce N40W 24.2' do

Bearings are magnetic. Distances to notch in lower blaze.

(M8) Found 1" pipe with 4" alum. cap.


Blazed and scribed the following:

4" Maple N21E 31.1' "1/4S NBT"

12" W.Spruce S36W 19.2' do

13" W.Spruce S57W 10.2' do

The 1972 wit: 12" W.Spruce S86.5E 19.6' with overgrown blazes. Bearings are magnetic. Distances are to notch in lower blaze.



Signed by Stephan J. Szyszkoski  
 Surveyor's Michigan License No. 33986

Date 10/31/00

For the Michigan Department of Natural Resources - Forest Management Division