

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 52N R 36W	L11
	T	
	T	
2. Property Controlling in Section	S	
	S	
	S	
3. Miscellaneous Property in Sec.	S	
	S	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 05/28/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Quarter corner common to Sections 25 and 36. 1846 - Established by Sylvester Higgins and Hiram Higgins, Deputy Surveyors, on the Section line between Section corners 39.95 chains east and 39.96 chains west. Set post. Sugar 8" N75E 22 links, Y.Birch 13" S70W 24 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner on the Section line between monumented Section corners 2496.67' west and 2496.02' east, being proportionate to the original record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Maple N12W 21.0' mrkd "1/4S NBT"
7" Maple N64E 17.1' do
14" Sugar S07W 14.35' do
15" Sugar N82W 15.8' do
Set sq'd cedar post adjacent.
E= 7861581.723 N= 233072.281



Bearings are magnetic. Coordinates are MCS83 in meters (NAD83 (2011))
Coord. Ref.=NGS PID RL0503: N= 233736.671 m. E= 7856830.966 m.

Signed by Stephan J. Szyszkoski Date 07/30/2013
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division