

DEC 14 1998

SECTION

APPROVED BY THE SURVEYOR  
Houghton County

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Nov. 6, 1998  
Robert W. Crampton  
For corners in

Houghton County Located in: Corner Code #

- |                         |   |           |             |
|-------------------------|---|-----------|-------------|
| 1. Public Land Survey   |   | T53N R32W | MC E3-F3 Z2 |
|                         |   | T53N R32W | MC E3-E4 Z3 |
|                         |   | T R       |             |
|                         |   | T R       |             |
| 2. Property Controlling | S | T R       | #3          |
| in Section              | S | T R       |             |
| 3. Miscellaneous        | S | T R       |             |
| Property in Sec.        | S | T R       |             |

ROBERT F. MIKESCH 11/11/98  
HOUGHTON COUNTY, REGISTER 09:42  
LC 3/ 524 PAU Fee: 9.00  
Page 1 of 1

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

4. Lot No. , Recorded Plat  
5. Private Claims

I, Steven C. Hein, in a field survey on September 4, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC E3-F3 Z2: From original notes: East between Sections 4 & 9; 29.83 Intersect Keweenaw Bay; Fir 7 for Meander Corner on ledge of sand rock about 15 feet high; fir 3 N20W 11. No evidence of original corner or accessories found.

MC E3-E4 Z3: From original notes: South between Sections 8 & 9; 25.40 Intersect Keweenaw Bay; Spruce 7 for Meander Corner on vertical ledge of sand rock about 65 feet high; Spruce 10 N25W 06. No evidence of original corner or accessories found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC E3-F3 Z2: Found 1/2" capped pipe, P.S. 24591, 5" A.G., 10' East to ledge, as shown on survey by R. W. Crampton dated July 17, 1996. Witnesses as shown on survey: 5" Maple N20°W 39.66'; 6" W. Birch S77°W 44.25'; 5" Maple N75°W 27.13'; 5" Balsam N52°W 3.48'

MC E3-E4 Z3: found 1 1/4" pipe, 24' South to top of ledge, pipe fits W. W. Stockley breakdown of Section 8 from around 1920. No apparent Witnesses. Accepted pipe as best available evidence of line between Sections 8 & 9.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC E3-F3 Z2: Set 2 1/4" Brass Cap on 1/4" pipe, 6" A.G., 10' East to ledge

Witnesses (check):  
5" R. Maple N23°W 39.64'  
6" W. Birch S77°W 44.21'  
5" R. Maple N80°W 27.13'  
5" Balsam N52°W 3.48'

MC E3-E4 Z3: Set 2 1/4" Brass Cap on 1/4" pipe 4" A.G., 24' South to top of ledge

Witnesses:  
6" W. Birch N54°E 9.29'  
6" Balsam S86°W 20.85'  
9" W. Birch N51°W 33.39'  
20" R. Maple N04°W 25.23'  
Reset 1 1/4" pipe 1' So. of Brass Cap



Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by Steven C. Hein

Date Oct. 31, 1998

Surveyor's Michigan License No. 32336