ΑP	PROVI		Wat.	CORNE
1	F.A	3/15	()E	[990
٠:	Hou	ghto	a C	ounty

Nov.	6,1198 W. Campo
Q.l. 4	W. Courts
المحمد ويوال أراسا	

MEANDER-5.

NOT SET

-AND	CORNER	RECURDA	MOLLA	JEK I IF	CAIL
Filing	Requirem	ent of Act	74, Mic	ch. P.A.	1970

E of MICHIGA

ROBERT W. CRAMPTON LAND SURVEYOR NO.

SONAL

For corners in	' Filing Requi	irement of Act 74, Mich. P.A. 1970	UEC 1 4 1998	
For corners in HOUGHTON (County)	Located In:	Corner Code #		
Public Land Survey	T <u>53W</u> R <u>33W</u> T R T R	ROBERT F. MIKE		
Property Controlling in Section	ST R ST R	HOUGHTON COUNT LC 3/545	Figure 199	
3. Miscellaneous	S T R		Page 1 of 1	
Property in Section	S T R		ber	
7. Private Claims	in a field survey on, in a field survey on, in a field survey on, in conformance with regulations and tions of the United States Departure of a Court of Law and/or that the ance with the rules of the Michigan	OCTOBER 22, 19 98 P.A. of 1970, the corner points mentioned drules therefore as required in the current trent of the Interior, Bureau of Land corner points mentioned in lines 3, 4 and Board of Professional Surveyors or by a ented, re-monumented, recovered, found	A B C D E F G H 1 J K 2 6 5 4 3 2 3 4 2 3 4 4 7 8 9 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	12
NOTE: Not more than 4 on this certification	4 corners, all in the same town ar te.	nd range, may be recorded	11 32 33 34 35	
A. Description of original	inal monument and accessories	and/or subsequent restoration:	13	L
MEANDER-13,	SET MEANDER POST, 1334.52 N51W 20, Y. BIRCH TREE 10,	2' EAST OF SOUTHWEST CORNER OF S60W 14.	SECTION 12, SPRUCE 6,	

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - MEANDER13, FOUND 1 1/2" IRON PIPE, FROM SURVEY BY EWART MULLER DATED JULY 1980, AND SURVEY BY U.P. ENGINEERS & ARCHITECTS, INC. DATED 10/26/95.
 - MEANDER-5, FOUND 6" SQUARE CONCRETE U.S.G.S. MONUMENT FROM CORPS. OF ENGINEERS, NOTE DATED OCT. 19, 1929. IN OLD DOWN FENCE LINE NORTH AND SOUTH. SECTION 12,
- C. Description of monument for corner and accessories established to perpetuate locating the position of the
 - MEANDER-13 LEFT 1 1/2" IRON PIPE IN PLACE, AND PLACED 2 1/4" BRASS CAP. FOUND BRASS TAGS (U.P. ENG. #18983) NAILED TO 10" W. PINE TREE S52°E 22.37', 10" W. PINE TREE S41°W 17.61', 7" W. PINE TREE N80°W 16.83', 8" W. PINE TREE N59°W 9.36'.
 - MEANDER-5 LEFT MONUMENT IN PLACE, PLACED 1 1/4" IRON PIPE WITH 2 1/4" BRASS CAP NEXT TO MONUMENT. WITNESSED WITH SURVEY TAG NAILED TO: 8" ASPEN TREE N37°W 28.26', 6" HEMLOCK TREE N31°E 18.42', 5" BALSAM TREE S49°E 16.28', 14" H. MAPLE TREE S46°W 14.23',

Signed by Ball W. Canto	Date Nov. 4, 1995
Surveyor's Michigan License No. 2459/	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
	REVISED MAY 14, 1975 REVISED JAN., 1983