

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton Located In: Corner Code #
1. Public Land Survey T 53N R 35W 111
2. Property Controlling in Section S 35 T 53N R 35W 3
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 10/01/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I11) Corner common to Sections 26-27-34-35. 1846 - Established by S.W.Higgins, Deputy. Set post. Sugar 10" S42°W 39 links, Hemlock 9" N28°E 48 links. 1961 - Remonumented in the original position by Billy D. Buckler RLS, at record bearing and distance from the stump of the Hemlock BT and stump hole of the Sugar BT. Set 1" I.pipe with 4" brass cap. 16" Y.Birch N78°W 37.5 links, 6" Soft Maple N40°E 19 links.

(3-Sec. 35) North 1/16 corner between Sections 34 and 35. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I11) The 1961 monument was found in good condition and at record bearing and distance from the 1961 NBT Maple N40°E, 19 links, now 11" d.b.h. The Y.Birch NBT was not recovered. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(3-Sec. 35) Established the position for the corner midway and on the Section line between Section corner 1323.21' north and Quarter corner 1323.21' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I11) Found 1" ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
11" Maple N46°E 13.1' old blazes (1961 NBT)
4" Sugar S69°E 13.4' mrkd "S35 NBT"
7" Maple S27°W 7.15' "S34 NBT"
9" Maple N39°W 14.25' "S27 NBT"
Set sq'd cedar post adjacent.
E= 7868991.957 N= 242537.398

(3) Set 1" IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
10" Sugar N12°E 6.0' mrkd "1/16S BT"
9" Sugar S78°E 16.25' do
14" Sugar S33°W 22.95' do
4" Sugar S87°W 5.45' do
Set sq'd cedar post adjacent.
E= 7868982.276 N= 242134.230

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by [Signature]
Surveyor's Michigan License No. 33986

Date 11/04/2015

For the Michigan Department of Natural Resources, Forest Resources Division

