

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 12 T 55N R 33W	11
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on 08/02/2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11-Sec. 12) Southwest 1/16 corner, Section 12. Previously monumented in 1998 by R.W.Crampton, PS 24591, at a position determined by a mathematical subdivision of Section 12. Set 1/2" capped iron pipe. Mr. Crampton reports a distance west to 1/16 corner #10 of 1294.61' and an angle in the NE quadrant at 1/16 cor. #10 between the Section and 1/16 lines of 90 deg. 20'42".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 12) Recovered the 1998 monument, a 1/2"ID I.pipe with plastic cap #24591, set in concrete, not conforming to the location shown on Mr. Crampton's survey (drawing no. 5-2-1792). Specifically, the distance west from Mr. Crampton's iron to #10 was found to be 1290.81' and the angle formed with the Section line at #10 in the NE quadrant was found to be 90 deg 36'34". Mr. Crampton reports that he did not set his pipe in concrete and I therefore conclude, and Mr. Crampton concurs, that the pipe is not in the original position and I do not accept it. Reestablished the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, 1/16 corners #10, #12, and #15 being monumented and of record. #12 is shown on recorded surveys by J.I.Haataja PS 19883, dated 1993 and 1995, and is monumented with a square iron pin.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
11" Sugar N40E 10.9' no blaze or marks  
6" Y.Birch S66E 8.7' do  
12" Maple S27W 15.4' mrkd "1/16S BT"  
6" Maple S64W 18.85' do  
1/2" capped pipe S81W 4.0' not accepted.  
Set sq'd cedar post adjacent.  
Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 11/15/2011  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Management Division