

JAN 19 2001

SECTION

2000 REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filling Requirement of Act 74, Mich. P.A. 1970

For Corners in BINGHAM Township

Huron  
(County)

Located in:

Corner Code #

1. Public Land Survey

T 15N R 13E

A - 11

T R

T R

T R

2. Property Controlling  
in Section

S

S

T R

T R

3. Miscellaneous  
Property in Sec.

S

S

T R

T R

STATE OF MICHIGAN  
HURON COUNTY  
RECORDED

8 DEC 2000 9:57 AM

FRANCES L. HOLDWICK  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Russell L. Brown, in a field survey on June 2, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1834 G.L.O. H. Parke D.S. Set Post Corner Section 25 and 36 East Side T15N-R12E, Lynn 7, S4W 17, DO 7, N17W 15

COUNTY SURVEYORS RECORD - None

COUNTY ROAD COMMISSION RECORDS Iron Pin, Witnesses: Iron Pin N45°E 83.0', Spike T.P. N70W 87.7'

L.C.R.C. - None

RECORDED SURVEYS - None


UNRECORDED SURVEYS - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner or accessories found.

Found 3/4" Dia. Re-Rod in Monument Box.

Accepted Found 3/4" Re-Rod as best evidence of original corner position.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11 N. W. Cor. Sec. 31, S. W. Cor. Sec. 30, T15N-R13E

Found 3/4" Dia. Re-Rod in Monument Box

WITNESSES:

N50°W 41.68' Notch N. end 18" C.M.P.

S45°W 50.05' to Nail & Washer Ped. Support Post

S50°E 81.28' to Spike in N. E. Face of Power Pole

N60°E 73.40' to Notch in N. End 48" C.M.P.

South 2630.67' A-12 W. 1/4 Cor. Sec. 31, T15N-R13E

North 2636.96' A-10 W. 1/4 Cor. Sec. 30, T15N-R13E

NOTE:

This Corner is common with M-11,  
T15N-R12E

Signed by Russell L. Brown  
Surveyor's Michigan License No. 24588

Date Nov. 2, 2000

Peer group approved at meeting held November 2, 2000. RLB