

JAN 19 2001

2000 REMONUMENTATION

Re Mon Liler 2, Page 79

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Huron	Located in:	Corner Code #
(County)		
1. Public Land Survey	Sherman	T15N R16E A-6
		T R
		T R
		T R
		T R
2. Property Controlling	S	T R
In Section	S	T R
3. Miscellaneous	S	T R
Property in Sec.	S	T R

STATE OF MICHIGAN
HURON COUNTY
RECORDED

20 SEP 2000 2:06 PM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Charles S. Getz, in a field survey on May 10, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6		5			4		3		2		1
3												
4	7		8			9		10		11		12
5												
6	18		17			16		15		14		13
7												
8	19		20			21		22		23		24
9												
10	30		29			28		27		26		25
11												
12	31		32			33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:
A-6 1834 G.L.O., H. Parke D.S. County Road Commission Records - NONE
Set quarter section post Recorded Surveys - NONE
Birch 20", South, 15 1/2 Links
Lynn 20", N49°W, 11 Links Unrecorded Surveys - NONE
L.C.R.C. - NONE


County Surveyor Records -
NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-6
W 1/4 Cor, Section 18, T15N-R16E
Found 1" Iron Bar, on top of Large Culvert (Fill Area)
Accepted as the best available evidence
of the original corner position
(On Edwards Road)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-6
W 1/4 Cor, Section 18, T15N-R16E
Found 1" Iron Bar
East 15.55' to Nail in Guard Rail Post
N45°W 23.5' to Nail in Guard Rail Post
S45°E 24.95' to Nail in Guard Rail Post
S45°W 25.60' to Nail in Guard Rail Post
N45°E 23.8' to Nail in Guard Rail Post
South 2623.69' to SW Cor, Sec 18, T15N-R16E
North 2629.21' to NW Cor, Sec 18, T15N-R16E



Signed by Charles S. Getz
Surveyor's Michigan License No. 25843

Date June 3, 2000

PEER GROUP APPROVED AT MEETING
HELD September 18, 2000. RLB