

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Re-Mon Leher 2, Page 8

Huron
(County)

Corner Code #

STATE OF MICHIGAN
HURON COUNTY
RECORDED

29 NOV 2000 11:21 AM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land survey: **Sebawaing** T 15 N R 9 E A-5
T _____ R _____ A-6 ☒
T _____ R _____
T _____ R _____ SURVEY &
2. Property Controlling S _____ T _____ R _____ DOCUMENTATION
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____ JAN 19 2001
4. Lot No. _____, Recorded Plat _____ SECTION
5. Private Claims

I, James T. Meek, in a field survey on October 1, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
Original survey, West Bdy. T15NR9E, 1835, Harvey
Parke D.S.

A-5 Corner of Sections 7, 18
Post
W. Oak 24", S48°E, 4 chains
W. Oak 16", N69°E, 4 chains 25 links

County Surveyor's Record: none
Recorded Surveys: none
LCRC: none

A-6 West ¼ Corner of Section 18
Not monumented

County Surveyor's Record: none
Recorded Surveys: L1, P53
LCRC: none

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-5 Corner of Sections 7, 18

State of Michigan Brass cap in concrete
Stamped T15NR9E
Accepted as best available evidence of
the original corner position

A-6 West ¼ Corner of Section 18

Found 5/8" iron
Accepted as best available evidence of the
original corner position
Set 1/2" iron w/cap #39089 at intersection
with line from M-4 to M5, T15NR8E

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-5 Corner of Sections 7, 18
State of Michigan Brass cap
From which:
¾" pipe w/cap bears N2°E, 66.0'
¾" pipe w/cap bears N30°E, 37.6'
Tag in willow bears N10°W, 37.7'
Tag in Ash bears North, 110.8'
M-3, T15NR8E Corner of Sections 1 & 12,
bears N0°01'23"W, 33.0'
M-4, T15NR8E East ¼ corner of Section
12, bears S0°01'23"E, 2610.46'

A-6 West ¼ Corner of Section 18
¼" iron w/cap #39089
From which:
Tag in power pole bears S70°W, 26.2'
Tag in power pole bears S80°W, 100.2'
Tag in power pole bears N65°W, 91.7'
1" pipe bears N35°W, 55.8'
M-4, T15NR8E East ¼ corner of Section 12, bears
N0°01'23"W, 39.07'
M-5, T15NR8E Corner of Sections 12 & 13, bears
S0°01'23"E, 2604.38'

Signed by

Date

Surveyor's Michigan License No. 39089

APPROVED AT PEER BOARD MEETING 11-02-00 RLB



REVEYORS, JAN. 28, 19
REVISED MAY 14, 19
REVISED JAN, 19
REVISED OCT. 19