

2000 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Re-Monumented 2, Page 91

For Corners in

Huron
(County)

Located in:

Corner Code #

STATE OF MICHIGAN
HURON COUNTY
RECORDED

29 NOV 2000 11:21 AM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

1. Public Land survey: Sebewaing T 15 N R 9 E

T R

T R

T R

T R

2. Property Controlling S T R

S T R

3. Miscellaneous S T R

S T R

Property in Sec. S T R

S T R

A-9

A-10

SURVEY &

REMONUMENTATION

JAN 19 2001

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

SECTION

5. Private Claims

I, James T. Meek, in a field survey on October 1, 2000

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expessed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original survey, West Bdy. T15NR8E, 1835, Harvey

Parke D.S.

A-9 Corner of Sections 19, 30

Post

Lynn 14", N25°W, 11 links

Beech 10", S6°E, 23 links

County Surveyor's Record: none

Recorded Surveys: none

LCRC: none

A-10 West ¼ Corner of Section 30

Not monumented

County Surveyor's Record: none

Recorded Surveys: none

LCRC: none

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-9 Corner of Sections 19, 30

Found no evidence of the original corner position

Set ½" iron w/cap #39089 at proportionate distance between M-7 & M8, T15NR8E Centerline of Wildner Road bears East

A-10 West ¼ Corner of Section 30

Found no evidence of the original corner position

Set ½" iron w/cap #39089 at proportionate distance between M-8 & M-9, T15NR8E

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9 Corner of Sections 19, 30

½" iron w/cap #39089

From which:

½" iron bears N1°E, 96.9'

Tag in 6" wood post bears N1°E, 92.0'

Tag in 4" Ash bears N25°W, 93.9'

½" iron bears N20°W, 81.8'

M-7, Corner of Sections 13 & 24, T15NR8E

bears N0°04'30"E, 63.94'

M-8, East ¼ corner of Section 24,

T15NR8E bears S0°04'30"W, 2572.98'

A-10 West ¼ Corner of Section 30

½" iron w/cap #39089

From which:

Tag in 9" Ash bears N2°E, 115.3'

Tag in wood post bears S70°E, 64.4'

Tag in 6" Elm bears N51°W, 75.2'

Top of pointed rock bears N25°W, 29.3'

M-8, East ¼ corner of Section 24, T15NR8E bears

N0°04'30"E, 71.35'

M-9, Corner of Sections 24 & 25, T15NR8E bears

S0°04'30"W, 2565.57'

Signed by

Date

Surveyor's Michigan License No. 39089APPROVED AT PEER BOARD MEETING 11-02-00RdB

FOR ADOPTED BY MICHIGAN BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995