SURVEY & REMONUMENTATION

JAN 2 2 1998

SECTIO	V
---------------	---

REMONUMENTATION Re-Mon Leber 1, Page 73
LAND CORNER RECORDATION CERTIFICATE

For corners in	ruir	ng Requirement of Act 74, M	lich. P.A. 1970	
Huron (County)	Located In:	Corner Code#		STATE OF HICHIGAN HURON COUNTY
1. Public Land Survey Sa	TR_ TR_	B-13		RECORDED 6 NOV 97 10:26 A.M.
Property Controlling in Section Miscellaneous Property in Sec.	S TR_ S TR_ S TR_ S TR_		Register	FRANCES L. HOLDWICK REGISTER OF DEEDS of Deeds Stamp & File Number
4. Lot No, Reco	rded Plat		A B C	D E F G H I J K L
conformance with regulations and United States Department of the that the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be	In Iran Williams therefore as required interior, Bureau of Land Malin lines 3, 4 and 5 above war a Decree of a Court of elow:	Aug. 17, 1997 do hereby star points mentioned in lines 1 and 2 at in the current manual of survey instruinagement or by a decree of a Court of vere in conformance with the rules of taw; established, re-established, manual established.	bove were in actions of the 5 Law and /or 6 —18	17 16 15 14 13 20 21 22 23 24
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town	and range, may be recorded	9 10 30 3 11 12 31 3	29 28 27 26 25
 Description of original more 	nument and accessories	s and/or subsequent restoration:	13 0 ··· 0 ··· 1 ···	
	H. Parke D.S.	County Surveyor Records	ds - NONE Unrocor	
B-13 1834 G.L.O., Set quarter section Hemlock 9", N61°W, Do. 11", N34°E,	post 13 Links 8 Links	Survey Liber 3, Page LAUGHLIN McDOWELL	425 - Axle Shaft in PLAT (Liber 3, Page	cake, L.C.R.C NONE d Surveys - NONE n Monument Box 38) - shows corner
 Description of corner evidence 	ence found and/or meth	od applied in restoring or reestab	olishing corner:	
A-13 SW Cor, Section 3 Found 3/4" Re-Rod Accepted as the b	31, T16N-R16E I in Monument Bo	B-13 S 1/4 0	or, Section 31, T xle Shaft in Monum	L6N-R16E ment Box

of original corner position (Intersection of Helena & Edwards Roads)

Accepted as the best available evidence of original corner position

. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SW Cor, Section 31, T16N-R16E
Found 3/4" Re-Rod in Monument Box
N45°E 74.88' to Nail in SE Side of Power Pole
S45°E 57.81' to Nail in NE Side of Cable Post
N40°W 51.53' to S. Point of Conc. Project Marker
West 2625.24' to S 1/4 Cor, Sec 36, T16N-R15E
East 2623.54' to S 1/4 Cor, Sec 31, T16N-R16E MINIMINING OF Mich,

B-13 B-13 S 1/4 Cor, Section 31, T16N-R16E Found Axle Shaft in Monument Box North 35.26' to W. End of 18" CMP N45°E 56.62' to E. End of 18" CMP South 34.98' to E. End of 36" CMP S45°W 44.52' to W. End of 36" CMP West 2623.54' to SW Cor, Sec 31, T16N-R16E East 2623.70' to SE Cor, Sec 31, T16N-R16E

₌rveyor's Michigan License No.

25843

RLB

EER GROUP APPROVED AT ETING NOVEMBER 5, 1997

Charles S. Getz Land Surveyor No. 25843 Principal Summer Summer

Date <u>October 12</u>, 1997

APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995