

REMONUMENTATION

JAN 22 1998

SECTION

REMONUMENTATION

Re-Man Labeled, Page 74

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Huron

(County)

Located in:

Corner Code #

1. Public Land Survey Sand Beach T16N R16E

T16N R16E

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

C-13

★ 1

STATE OF MICHIGAN
HURON COUNTY
RECORDED

6 NOV 97 10:26 A.M.

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Charles S. Getz, in a field survey on Aug. 17, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-13 G.L.O., H. Parke D.S. (1834)

Set Post

B. Ash 10", N76°W, 13 Links

Do. 10", N75½°E 3½ Links

Co. Surveyor Records - NONE, Co. Rd. Comm. Records - NONE
Recorded Surveys - NONE, Unrecorded Surveys - NONE
L.C.R.C. - NONE

G.L.O., H. Parke D.S. Meander Corner (1834)

Set Post on the border of Lake Huron

Sugar 14", N61½°W, 12 Links

Hemlock 9", S32°W, 9 Links

Co. Surveyors Records - NONE
Co. Rd. Comm. Records - NONE
Recorded Surveys - NONE, L.C.R.C. - NONE
Unrecorded Surveys - NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-13

SW Cor, Section 32, T16N-R16E

Found 1/2" Iron Bar

Accepted as the best available evidence of original corner position

GLO Meander Cor, Section 32, T16N-R16E
GLO Meander Cor falls in Lake Huron, original corner position is inaccessible
Set Witness Corner to GLO Meander Corner, 30.0' West of present day High Bank.
Used C-13 and monumentation of "LAUGHLIN McDOWELL PLAT" for line. Said Plat Recorded in Liber 3 of Plats, Page 38

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-13

SW Cor, Section 32, T16N-R16E

Found 1/2" Iron Bar (Capped)

N05°E 31.31' to Nail in W. Side of 15" Ash

N40°W 36.34' to Nail in W. Side of 24" Ash

S45°W 38.69' to Nail in W. Side of 36" Cottonwood

S10°W 32.15' to Nail in W. Side of 36" Cottonwood

West 2623.70' to S 1/4 Cor, Sec 31, T16N-R16E

East 1856.33' to Witness Cor to GLO Meander

Cor, Sec 32, T16N-R16E

Witness Cor to GLO Meander Cor, Section 32, T16N-R16E Set 1/2" Iron Pipe (Capped)

East 97.27' to Recorded Position of GLO

Meander Cor

East 30.0' to Top of Present Day High Bank

N80°W 80.67' to Nail in N. Side of 18"

Lombardi Poplar

S80°W 81.04' to Nail in N. Side of 12" White Birch

S40°W 69.10' to Nail in E. Side of 12" White Birch

West 1856.33' to SW Cor, Sec 32, T16N-R16E

Signed by Charles S. Getz

Surveyor's Michigan License No. 25843

Date October 12, 1997

PEER GROUP APPROVED AT
MEETING NOVEMBER 5, 1997.

RLB



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995