

JAN 19 2001

2000 REMONUMENTATION

Re-Mon. Ticket 2, Page 70

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Huron

(County)

Located In:

Corner Code #

STATE OF MICHIGAN
HURON COUNTY
RECORDED

20 SEP 2000 2:04 PM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey Sand Beach T16N R16E A-8
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6			5			4		3		2	1
3												
4	7			8			9		10		11	12
5												
6	18			17			16		15		14	13
7												
8	19			20			21		22		23	24
9												
10	30			29			28		27		26	25
11												
12	31			32			33		34		35	36
13												

I, Charles S. Getz, in a field survey on July 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
A-8 1834 G.L.O., H. Parke D.S. County Road Commission Records - NONE
Set quarter section post
Hemlock 18", S4°W, 26 Links Recorded Surveys - NONE
Do. 13", N21°W, 15 Links Unrecorded Surveys - NONE
L.C.R.C. - NONE

County Surveyor Records -
April 2, 1865, C B Cottrell,
2 Surveys refer to Corner

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
A-8
W 1/4 Cor, Section 19, T16N-R16E
Found 3/8" Bar (Bent) on North Side of 6" Square, 6' High, Concrete Post
Accepted as the best available evidence
of the original corner position
Replaced 3/8" Bar with 1/2" Re-Rod (Capped)

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
A-8
W 1/4 Cor, Section 19, T16N-R16E
Set 1/2" Re-Rod (Capped), replacing 3/8" Bar
on North Side of 6" Square, 6' High, Concrete Post
North 2622.77' to NW Cor, Sec 19, T16N-R16E
South 2643.70' to SW Cor, Sec 19, T16N-R16E



Signed by Charles S. Getz
Surveyor's Michigan License No. 25843

Date July 23, 2000

PEER GROUP APPROVED AT MEETING
HELD September 18, 2000 RLB