

JAN 19 2001

SECTION

2000 REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in CASEVILLE Township

Huron
(County)

Located in: Corner Code #

1. Public Land Survey T 18N R 10E K - 13
T _____ R _____
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S
in Section S T _____ R _____
3. Miscellaneous S T _____ R _____
Property in Sec. S T _____ R _____

STATE OF MICHIGAN
HURON COUNTY
RECORDED

8 DEC 2000 9:56 AM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Russell L. Brown, in a field survey on October 3, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners; all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

1834 GLO H. Parke D.S. Set post corner Sections 35 and 36, T18N-R10E
Sycamore 24 N44W 11; Hemlock 9 N86 1/2E 19

COUNTY SURVEYOR RECORD: None

COUNTY ROAD COMMISSION RECORD: Iron Pin: WITNESSES: Spike Power Pole 42.35'; Iron Pin N45W 48.0'

L.C.R.C.: None

RECORDED SURVEYS: None

UNRECORDED SURVEYS: None

RECORDED PLATS: None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner or accessories found.

Found 1" Pipe in Monument Box.

Accepted found 1" Pipe as best evidence of original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13, S. Corner Common to Sections 35 and Sections 36, T18N-R10E

Found 1" Pipe in Monument Box

WITNESSES:

N45°E 53.21' to Nail & Tag in S.E. Corner 6" x 6" Wood Post

S55°E 36.97' to 1/2" x 18" Steel Stake (Re-Rod) Set

S50°W 42.20' to Nail & Tag in S.E. Side Power Pole

West 31.38' to Nail & Tag in N. Side of Wood Post

East 1.90' to Centerline Asphalt surface Sturm Road

East 2613.15' to L-13, S. 1/4 Cor. Sec. 36, T18N-R10E

West 2639.36' to J-13, S. 1/4 Cor. Sec. 35, T18N-R10E



Signed by Russell L. Brown
Surveyor's Michigan License No. 24588

Date Nov. 2, 2000

Peer group approved at meeting held November 2, 2000. RLB