



LIBER 3 PAGE 224
REMONUMENTATION

128725 RECORDED
HILLSDALE CO. MICH.
'97 NOV 26 PM 4 07

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Jeffrey VanZandt
CLERK OF DEEDS

SURVEY &
REMONUMENTATION

FEB 11 1998

Register of Deeds Stamp & File Number

SECTION

HILLSDALE
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 6S R 1W

G-3

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Jeffrey A. Bieszk, in a field survey on 12 November, 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Robert Clark Jr. (1824)
10" Butternut N 81 E 128 lks
4" Butternut N 15 E 73 lks

County Survey (George Marks 1901)
Found Plow Point and Stone added tile
14.5" B. Walnut S 61.75 E 38.75 lks
12" Apple N 87 W 64.5 lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found no iron, dug at a location from proportional measurement from George Marks survey, found nothing. Set
iron at the proportionate location and accepted as a careful and faithful reestablishment of the position of the
original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box
6 ft. South and 3 ft. West of intersection of Waldron Road and North Adams Road.
Nail w/tag wood post N 45 W 58.25 ft.
Nail w/tag fence post S 50 E 50.70 ft.
Nail w/tag 12" Box Elder N 75 E 120.00 ft.
Road Sign Post S 35 E 54.55 ft.



Signed by [Signature] Date 25 November 1997

Surveyor's Michigan License No. 41093