

## LIBER 5 PAGE 34

## HILLSDALE COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FFCOR	DEU
HILLSCALL	COLMIGH.
00 OCT 11	EHO: UI

Jane Company

	For	corners	in
--	-----	---------	----

HILLSDALE	Located In:	Corner Code #	
ADAMS TWP.		•	
1. Public Land Survey	T <u>6S</u> R <u>2W</u> T R T R	<u>C-11</u>	
2. Property Controlling in Section	S T R S T R		
3. Miscellaneous Property in Sec.	S T R S T R	***************************************	Re
4 Lot No.	Recorded Plat		ı A

SURVEY & REMONUMENTATION

JAN 1 2 2001


SECTION

egister of Deeds Stamp & File Number

4.	Lot No	,	Recorded	Plat		
	Private Claims	,				

I, <u>Frederick J. Cutcher</u>, in a field survey on <u>Sept. 15</u>, <u>2000</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration:

GLO, Robert Clark, Jr., Apr. 1825: Set Post; B. Oak 15" N. 87° W. 178 lks.; B. Oak 16" N. 10-1/2° E. 128 lks.

Geo. Mark: Survey #930, May 30, 1882, stone; Survey #1016, Mar. 11, 1886, stone with brick.

Robert E. Burris, Sr., June 5, 1973: LCRC L. 1 - P. 303, #2518, set R.R. Spike (See LCRC).

Keyno J. Shellenbarger: Survey recorded Feb. 12, 1992, Liber 649, Page 23, #67926

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. spike at road surface. All of the references in above LCRC remain.

Dug at position of R.R. spike. Nothing else found.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced R.R. spike with 3/4" x 30" iron with remonumentation cap in monument box and is accepted as the best available evidence of the position of the original corner. 2.5' N. and 3' W. of centerline roads.

Found Nail & Spotter Util, Pole N. 45° W. 45.09

Set Nail & Spotter in 30" Oak S. 35° E. 51.23'

Set Nail & Spotter in 24" Oak S. 48° E. 55.06

Set Nail & Spotter in Util. Pole N. 82° E. 129.90'

Date Surveyor's Michigan License No. 24592

OF MICH CUTCHER PROFESSIONAL

24592

SURVEYORS, JAN. 28, 1971 OFEBSIONP M REVISED MAY 14, 1975 REVISED JAN., 1983

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL

REVISED OCT., 1995