LIBER 5 PAGE 36

034954

FECORDED HILLSDALF CO. MICH. 60 OCT 11 AHID: 1,1

garage Cangaria

HILLSDALE COUNTY REMONUMENTATION Filing Requirement of Act 74, Mich. P.A. 1970

LAND CORNER RECORDATION CERTIFICATE

For corners in	BUT OF PREDS
HILLSDALE Located In: Corner Code # (County) ADAMS TWP.	SURVEY & REMONUMENTATION
1. Public Land Survey T6S R2W E-11 T R T R	JAN 1 2 2001
T	SECTION Register of Deeds Stamp & File Num
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K 1
I, <u>Frederick J. Cutcher</u> , in a field survey on <u>Sept. 15</u> , <u>2000</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	4 7 8 9 10 11 5 6 18 19 20 21 22 23 9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 11 12 31 32 33 34 35
A. Description of original monument and accessories and/or subsequent restoration:	
GLO, Robert Clark, Jr., Apr. 1825: Set Post; Hickory 13" N. 36° E. 10 lks.; B. Oak 36" S. 58° W. 20 lks. Geo. Mark: Survey #934, Oct. 1882, Stone, Brick & Earthen, Swamp Oak 14" S. 72-1/4 lks. Geo. Mark: Survey #1002, June 1885; Stone & Brick, Hickory 10" N. 3/4° E. 144 lks. Robert E. Burris, Sr.: LCRC L. 1, P. 305, June 5, 1973, Set R.R. Spike (see LCRC) Russell Cole: Survey recorded 1975, L. 1, P. 444, Track Spike in blacktop; 30" Ash ES WNW 51.14". Keyno Shellenbarger: LCRC L. 646, P. 99, Dec. 27, 1991, Found R.R. spike (See LCRC)	E 75.31'; 15" Maple SW 50.42'; Pwr. Pole
B. Description of corner evidence found and/or method applied in restoring or reest	ablishing corner:
Found R.R. spike. All of Shellenbarger's references remain. Found two of Burris' references	erences.
Dug at position of R.R. spike. Nothing else found.	
C. Description of monument for corner and accessories established to perpetuate to	cating the position of the corner:
Replaced R.R. spike with 3/4" x 30" iron with remonumentation cap in monument box evidence of the position of the original corner. 1.5' N. of centerline E/W Road; 7' ± W. of centerline gravel road to S.	and is accepted as the best available

Found Nail & Spotter Util. Pole N. 55° W. 51.55'

Set Nail & Spotter 42" Oak S. 70° E. 108.70'
Set Nail & Spotter 32" Ash S. 62° E. 75.15'
Set Nail & Spotter Util. Pole N. 78° E. 105.30'
N.E. cor. brick porch S. 63° W. 125.10'

Signed by Stederich J. Cutcher.
Surveyor's Michigan License No._____

24592

of Micago CUTCHER PROFESSIONAL

PROFESSIONAL SURVEYORS, JAN. 28, 1971

PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995