



LIBER 5 PAGE 37

034955

HILLSDALE COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

HILLSDALE

(County)

ADAMS TWP.

Located In:

Corner Code #

1. Public Land Survey

T6S

R2W

E-11

T

R

T

R

T

R

2. Property Controlling
in Section

S

T

R

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Frederick J. Cutcher, in a field survey on Sept. 16, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Robert Clark, Jr., Apr. 1825: Set Quarter Post; Beech 6" N. 23° W. 21 lks.; Lynn 15" East 52 lks.

Geo. Mark: Survey #934, Oct. 5, 1882, Stone & Brick, Elm 30" N. 17-1/2° W. 123-1/2 lks.

Records of Ringenberg Engineering: 2-9-84, Railroad Spike Found; Pwr. Pole N. 25° E. 66.12'; 30" Maple N. 50° E. 46.54'; Pwr. Pole S. 25° E. 66.66'; Pwr. Pole N. 65° W. 82.77'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. spike about in centerline N/S road and 3.5' S. of centerline E/W road.
All of the references from records of Ringenberg Engineering remain.
Dug at position of R.R. spike. Nothing else found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced R.R. spike with 3/4" x 30" iron with remonumentation cap in monument box and is accepted as the best available evidence of the position of the original corner.
About in centerline N/S road and 3.5' S. of centerline E/W road.
Found P.K. W. side Elec. Serv. Pole N. 20° E. 66.05'
Found P.K. W. side Util. Pole S. 20° E. 66.71'
Found P.K. S.W. side Util. Pole N. 63° W. 82.74'
Top Cen. Tel. Stan. N. 37° E. 42.88'
Set Nail & Spotter Util. Pole S. 70° E. 106.30'

Signed by Frederick J. Cutcher

Date _____

Surveyor's Michigan License No. 24592