



LIBER 5 PAGE 41

HILLSDALE COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

034959

RECORDED
HILLSDALE CO., MICH.
00 OCT 11 AM 10:42

[Signature]
REG. CLERK

For corners in

HILLSDALE

(County)

ADAMS TWP.

Located in:

Corner Code #

1. Public Land Survey

T6S

R2W

J-11

T

R

T

R

T

R

2. Property Controlling
in Section

S

T

R

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No.

, Recorded Plat

5. Private Claims

I, Frederick J. Cutcher, in a field survey on Sept. 18 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Robert Clark, Jr., Apr. 1825: Set Quarter Post; Beech 6" N. 51° W. 8 lks.; Beech 8" N. 15° E. 12 lks.

Geo. Mark, Jan. 21, 1867, Survey #470; Stone & brick.

Alan E. Ringenberg, LCRC L. 1, P. 544 #4817, Jul. 21, 1977: None Found - Measured fences 1/2 mile East, North, West and one mile South, prorated existing lines to GLO and reestablished corner. Set R.R. Spike; S. 21° W. 31.41' P.K. Nail N.E. side 30" Maple; S. 70° E. 94.35' P.K. nail N. side 18" Elm; N. 43° E. 54.04' top telephone riser.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. Spike and one reference; tel. riser N. 43° E. 54.04'.
Dug at position of R.R. spike. Nothing else found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced R.R. Spike with 3/4" x 30" iron with remonumentation cap in monument box and is accepted as the best available evidence of the position of the original corner.

About in line with centerline road to North; 1' South of centerline E/W road; in line with tree row to South.

Top center tel. stan. N. 45° E. 53.63'

Set Nail & Spotter 10" Ash S. 65° W. 62.68'

Set Nail & Spotter 10" Ash S. 22° E. 34.86'

Cen. 2" Maple S. 45° E. 42.05'

Signed by

Frederick J. Cutcher

Date

Surveyor's Michigan License No.

24592

