



LIBER 3 PAGE 102
HILLSDALE COUNTY
REMONUMENTATION

107768

RECORDED
HILLSDALE CO. MICH.

'95 DEC 21 AM 11 14

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Hillsdale

(County)

Fayette Twp.

Located In:

Corner Code #

1. Public Land Survey

T 6 S R 3 W

C-3

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

SURVEY &
MONUMENTATION

JAN 30 1996

COMMISSION

Register of Deeds Stamp & File Number

Frederick J.

Cutcher

I, , in a field survey on December 18, 1995

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner common to Sections 5, 6, 7 & 8, Town 6 South, Range 3 West.

Original Government Survey, April 28, 1885, Robert Clark, Jr.: Set post; W. Oak 20 South 465 L; B. Oak 12 East 528 L.

Fred Cutcher, May, 1993: 1/2" iron rod in centerline Bunn Rd.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Fayette Twp.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron rod in centerline of Bunn Rd.

None of the above references were found.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1/2" iron rod with 3/4"x36" iron rod with cap (County issue) in monument box and accepted as the best available evidence of the position of the original corner.

In centerline of N/S road.

P.K. in W. side P.P. N. 45° E., 88.7'.

Nail in N. side 8" Oak S. 85° E., 115.54'.

Fd. nail S.W. side 36" Oak N. 29° W., 79.37'.

Fd. nail N. side twin Willow N. 60° W., 45.15'.

1/2" iron rod N. 80° W. 14.15'.

Signed by Frederick J. Cutcher
Frederick J. Cutcher

Date December 18, 1995

Surveyor's Michigan License No. 24592