



LIBER 3 PAGE 97  
HILLSDALE COUNTY  
REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

107583

RECORDED  
HILLSDALE CO. MICH.

'95 DEC 15 PM 1 04

Judy VanZandt  
REG. OF DEEDS

SURVEY &  
DOCUMENTATION

JAN 30 1996  
Register of Deeds Stamp & File Number  
COMMISSION

For corners in

Hillsdale

(County)

Located In:

Corner Code #

Fayette Twp.

1. Public Land Survey

T 6 S R 3 W

H-3

T R

T R

T R

2. Property Controlling  
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Frederick J.

Cutcher

I, in a field survey on November 21, 1995

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Survey, 1825, Robert Clark, Jr.: Set stake, B. Oak 14 in. N. 62° W., 29; B. Oak 12 in. S. 13° W., 84.

Survey 1095, June 4, 1889, R.J. Coryell: Stone & earthen (no witnesses).

LCRC Liber 1, Page 411, June 19, 1974, A. John Hatt: Iron rail fence corner at intersection fences N-S-E-W.

1974, Black Cherry Hills Sub., Liber 10, Page 19: Iron rail post in concrete at N.E. cor. of Lot 9.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron rail post in concrete at N.E. cor. of Lot 9, Black Cherry Hills. In intersection of E/W/S fencelines (no evidence of fence line to North).

None of original references were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Did not replace iron rail post in concrete and is accepted as the best available evidence of the position of the original corner.

In intersection E/W/S fencelines.

Nail S. side of 18" twin Oak S. 50° W., 8.1'.

Nail N.W. side of 18" Oak S. 10° W., 7.9'.

P.K. S. side wood cor. post East 1.5'.

Cen. 4" Hickory N. 80° W., 25.3'.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Fayette Twp.



Signed by Frederick J. Cutcher

Date December 5, 1995

Surveyor's Michigan License No. 24592