

1993

LIBER 3 PAGE 16

COMMISSION

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

88318

RECORDED
HILLSDALE CO. MICH.

'93 DEC 22 PM 2 20

Judy VanZandt
REG. OF DEEDS

For corners in

Hillsdale

(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|---------------------------|------------|
| 1. Public Land Survey | T <u>6S.</u> R <u>3W.</u> | <u>I-7</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous | S _____ T _____ R _____ | _____ |
| Property in Sec. | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Frederick J. Cutcher

I, _____, in a field survey on December 22, 19 93

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

LCR dated Nov. 22, 1971 by A. John Hatt and recorded in Liber 1, Page 61:

Hatt set a P.K. Nail in pavement 4.88 feet East of an iron found. Iron found did not fit occupation East or roads and irons found West of Hillsdale Street.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On this date I found P.K. Nail set by A. John Hatt fitting references and information shown on LCR by A. John Hatt.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced P.K. Nail with 3/4" x 36" steel rod with cap (County issue) in monument box.
4.88' East of iron in pavement.
S.E. cor. of Garage S 88° W 84.00' to siding
Top of fire hydrant S 26° E 82.88'
Center of Man Hole (gate well) S 26° E 65.44'
Center of Man hole (gate well) S 15° E 76.10'
N.E. cor. of house N 55° W 81.84' to siding

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by Frederick J. Cutcher
24592

Date December 22, 1993

Surveyor's Michigan License No. _____