



LIBER 5 PAGE 51

035919

RECORDED  
HILLSDALE CO. MICH.

00 NOV 13 AM 11:09

HILLSDALE COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970Judy Vanlander  
REG. OF DEEDS

For corners in

HILLSDALE

Located in:

Corner Code #

(County)

PITTSFORD TWP.

## 1. Public Land Survey

T7S R1W K-7

T R

T R

T R

T R

2. Property Controlling  
In Section

S T R

S T R

## 3. Miscellaneous

S T R

Property in Sec.

S T R

SURVEY &  
REMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp &amp; File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Frederick J. Cutcher, in a field survey on Nov. 8, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

## A. Description of original monument and accessories and/or subsequent restoration:

GLO, Robert Clark, Jr., 1824: Set Post; Beech 24" S. 13° W. 10 lks.

LCRC L. 2, P. 3, Mar. 24, 1980, Kenneth Suydam, P.S. #17636: Found P.K. 2.0' South of centerline; spike in pole S. 40° E. 58.47'; cen of conc. C.B. gate N. 35° E. 52.44'; S.E. cor. bldg. fdn. N. 45° W. 71.40'.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found P.K. nail and all of Suydam's references.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced P.K. with 3/4" x 30" iron with remonumentation cap in monument box and is accepted as the best available evidence of the position of the original corner.

2' South of centerline M-34 and about in centerline Elm Road.

Nail &amp; spotter pwr. pole S. 35° E. 58.75'

Face 6" dia. gas valve post S. 30° W. 59.05'

Top cen. tel. stan. N. 38° E. 63.80'

S.E. cor. bldg. fdn. N. 30° W. 71.40'

Signed by Frederick J. CutcherDate 11/13/2000Surveyor's Michigan License No. 24592