

DEC 14 1993

LIBER 8 PAGE 57

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

Ingham
(County)

Located In:

Corner Code #

- 1. Public Land Survey T 4N R 1E G-1
T _____ R _____
T _____ R _____
T _____ R _____
- 2. Property Controlling in Section S _____ T _____ R _____
S _____ T _____ R _____
- 3. Miscellaneous Property in Sec. S _____ T _____ R _____
S _____ T _____ R _____

DEC 29 31 AM '93

REGISTER OF DEEDS
Paul Johnson
INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

- 1. Lot No. _____, Recorded Plat _____
- 2. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	6	5	4	3	2	1					
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

Marvin Fouty, in a field survey on Sept. 11, 1993, to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

1. Post set in original Government Surveys by Joseph Wampler D.S. in March 1826 with the following witnesses:
Ash 9 S44W 17 (11.2').
Elm 10 S60E 13 (8.6') - He reported intersecting the Township line 202 (133.3') East of Post

2. A. P. Drake, County Surveyor reported using corner in a survey dated March 1879 and recorded in Vol. 3, Page 143, Ingham County Surveyor's Records with no mention of monument and the following witnesses:
R. Oak 12 South 14 (9.2')
W. Oak 9 S82 1/2E 24 (15.8') (Continued on Back)

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Searched at the probable location of the corner and found Surveyor Bryan's 1/2" bar and cap and all of his witnesses. Traversed the North line of Section 3, T4N, R1E and found 1/2" bar and cap to be on the Township line but only 131.30 feet East of the Southwest corner of Section 34, T5N, R1E, Set standard bar and cap 2.00 feet east of found 1/2" bar to match the GLO falling of 133.30 feet.
Dug 8'X4'X2' deep hole and found no historic evidence of corner

Field work conducted by David Clifford, PS No. 25837
Traverse field notes are in book WMI pages 15-22 and 31-38

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard 3/4" x 24" Ingham County Remonumentation bar & PA 345 Cap #18989
Set Nail & Tag #25837 (D. Clifford) in SE side 11" Maple AZ 250° 24.62'
Set Nail & Tag #25837 in SW side 30" Oak AZ 104° 18.82'
Set Nail & Tag #25837 in East side 8" Oak AZ 350° 29.6'
Set Nail & Tag #25837 in West side 12" Hickory AZ 121° 59.85'
SW corner Sec. 34, T5N, R1E, (28" Hickory) AZ 270° 133.30'



signed by Marvin Fouty
Surveyor's Michigan License No. 18989

Date Nov. 24, 1993

3. This corner is not recorded.

4. Surveyor Larry Bryan LS #25832 reported setting the corner in an unrecorded survey dated July 9, 1992 as a set 1/2" bar and cap 3' North of fence with the following witnesses:

Set PK Nail East side 12" Maple S60°W 22.9'

Set PK Nail NE side 6" Basswood S15°E 8.40'

Set PK Nail SE side 10" Oak N15°W 29.16'

Set PK Nail South side 40" Oak East 20.67'

Southwest corner Sec. 34, Woodhull Township, West 133.0'