LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	_ Located In:	Corner Code #			
 Public Land Survey Property Controlling in Section Miscellaneous Property in Sec. 	T R R T R R S 33W S 33 T 42N R 33W S T R S T R S T R S T R S T R	F12 PCC N. of F12		2	
	corded Plat		Register of	Deeds Stamp & File	Number
above were in conformance with instructions of the United States I a Court of Law and /or that the co	74, Michigan P.A. of 1970, the corner regulations and rules therefore as required Department of the Interior, Bureau of Lacorner points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	ed in the current manual of survey and Management or by a decree of 15 above were in conformance with	y 5 of 6 18 1	7 16 15 22 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	-14 -13 -23 -24
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and range	, may be recorded	10 30 29	9 26 27	2625

A. Description of original monument and accessories and/or subsequent restoration:

(F12) Center of Section 33. 1972 - The E-W 1/4 line of Section 33 was monumented by William R. Donnan RLS 17618, and was recorded in a Certificate of Survey in L.1 of Surveys, Pages 2 to 5E, Iron County Records. The Center of Section was not monumented in that survey, but 1/16 corner #9, Sec. 33 was monumented. 1996 - Gary Pisoni, RLS 27457 monumented the corner position at the intersection of The Center of Section was not monumented in that survey, but 1/16 corner #9, Sec. 33 a straight line connecting the monumented East and West 1/4 corners with the N-S 1/4 line. The East 1/4 corner position used by Mr. Pisoni was not the position used by Mr. Donnan.

(PCC North of F12) Not previously established. A point on the N-S 1/4 line of Section 33 on the south side of Armstrong Creek, being a Traverse Point at the end of a Traverse Line along the Creek as shown on a Certificate of Survey by the undersigned, dated November 3, 2011.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F12) I retraced and recovered the 1972 E-W 1/4 line monumented by W.R.Donnan and accepted that line as the E-W 1/4 line of the Section. I recovered a capped iron placed by Gary Pisoni for F12 and accepted it as marking the N-S 1/4 line. I monumented the position for F12 at the intersection of the 1972 Donnan line with a straight line between Quarter corner F11 (rec. L7 of LCR, P.59) and the Gary Pisoni monument. Mr. Pisoni's monument was found to be 8.26' north of F12 as described herein.

(PCC North of F12). Established the position for the corner on a straight line between Quarter corner F11 (rec. L.7 of LCR, P.59) and Center of Section 33 recorded this date. The position is 24' south of the water's edge of Armstrong Creek, 952.56' north of Center of Section F12, and 1665.19' south of Quarter corner F11.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F12) Set 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 8" Poplar N21E 35.7' mrkd "PCC BT" 8" Poplar N50E 34.8' old blazes 9" J.Pine S05E 83.7' mrkd "PCC BT" 10" Poplar S31W 69.7' do Set sq'd cedar post adjacent. Bearings are magnetic.	(PCC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 4" Tamarack S73E 25.2' mrkd "PCC BT" 2" Tamarack S44E 12.4' "X X" 6" Tamarack N76W 30.9' "PCC BT" Found an iron fence post S03W 37.4' Set sq'd cedar post adjacent. Bearings are magnetic.

Signed by

12/27/2011

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD

AND SOL ised Jan., 1983 Rervised Oct., 1995

STEPHAN J

SZYSZKOSK

LAND SURVEYOR

(Armstrong

16785 16786