

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 42N R 33W	E12
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on Feb. 21, 2013 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

The Quarter corner was remonumented or reestablished by William R. Donnan PS #17618 and is shown on
a survey recorded in Liber 1, Pages 2-5E, Iron County Records, dated 12/12/1972. Set 4" square
concrete monument. No witnesses noted.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 1/2" rebar encased in a 4" square concrete monument in good condition, projecting about 1
foot above the ground. The position of the monument checks for line and distance with monuments to
the east, on the E-W 1/4 line of Sec. 33, as shown on the referenced survey. I accepted the
monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1/2" rebar in 4" square concrete monument.
Set measuring nail with MDNR tag in the side of:
7" Maple in clump N39°E 23.1' mrkd "1/4S NBT"
6" Maple S71°E 22.5' do
8" Maple S35°E 18.6' do
4" Maple S08°E 22.95' do
E=7887656.732 N=135483.785

Bearings are magnetic. Coordinates are MCS83 in meters.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/07/2013



For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995