

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 35 T 42N R 33W	14
	S 35 T 42N R 33W	16
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on Feb. 26, 2013 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 35) South 1/16 corner between Sections 35 and 36. Not previously monumented.

(16-Sec. 35) East 1/16 corner between Sec. 35 T42N-R33W and Section 2 T41N-R33W. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 35) Established the position for the corner midway and on the Section line between Quarter corner 1314.22' north and Section corner 1314.22' south.

(16-Sec. 35) Established the position for the corner midway and on the Township line between Quarter corner 1320.58' west and Section corner 1320.58' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 5/8"x28" rebar with plastic MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Poplar N40°E 65.5' mrkd "1/16S BT"
7" Poplar N69°E 34.6' do
8" Poplar S37°E 24.0' do
3" Cherry N30°W 54.0' " X X "
E=7892487.982 N=134980.417

(16) Set 5/8"x28" rebar with plastic MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Poplar N89°E 14.7' mrkd "1/16S BT"
5" Poplar S21°E 21.1' do
7" Poplar S22°W 32.1' do
4" Poplar N28°W 13.5' do
E=7892081.620 N=134585.903

Bearings are magnetic. Coordinates are MCS83 in meters.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/07/2013

For the Michigan Department of Natural Resources, Forest Resources Division

